

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2018 Levee Inspection Results

Reclamation District No. 0070 Meridian

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Reclamation District No. 0070 Meridian

Waterway			Bank	Unit Miles
Unit No. 01 Sutter Bypass			Right	7.92
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/15/2018 - 3/15/2018			
DWR Inspector	Bob Duffey			
Accompanied By	Andy Duffey			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0070_01_f_2015_12				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	13
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0070_01_s_2013_13				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0070_01_s_2013_14				
Comment Code					
Inspector Comment					
The LMA completed flood fight training in 2014.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.42	Rating **	M	Issue No.	41
LM End	0.42	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.141519 °	39.141519 °
				-121.839585 °	-121.839585 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23463
DS_ID:21347
EP_NO: 3804
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Unable to confirm if the indicators that were found in the field correspond to this crossing. Will need to contact PG&E to confirm location of crossing. Photos will need to be updated if the photos attach do not correspond to this crossing. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0304 for 12 inch gas pipe. Coordinates between DWR UCIP and USACE PI are approximately 630 feet apart.
FIELD_STRUCT_DESC: 12-inch coated steel natural gas pipeline through the levee, 3.6 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Marker sign on the waterside (WS) shoulder. Rock revetment on the WS slope. (Plans for installation of a 12-inch gas collecting line through the levee authorized under Permit No. 3804, 1961 - Pacific Gas and Electric Company [PG&E]).
[Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	0.42	Rating **	M	Issue No.	41 (cont)
LM End	0.42	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23463_40622.jpg



View of waterward side--no markers visible.

Photo 2 of 3 : UCIP_SP_2018_23463_40621.jpg



View of landward side where gas line markers are visible approximately 900 feet from levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.42	Rating **	M	Issue No.	41 (cont)
LM End	0.42	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.141519 °	39.141519 °
				-121.839585 °	-121.839585 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23463 DS_ID:21347 EP_NO: 3804 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Unable to confirm if the indicators that were found in the field correspond to this crossing. Will need to contact PG&E to confirm location of crossing. Photos will need to be updated if the photos attach do not correspond to this crossing. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0304 for 12 inch gas pipe. Coordinates between DWR UCIP and USACE PI are approximately 630 feet apart. FIELD_STRUCT_DESC: 12-inch coated steel natural gas pipeline through the levee, 3.6 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Marker sign on the waterside (WS) shoulder. Rock revetment on the WS slope. (Plans for installation of a 12-inch gas collecting line through the levee authorized under Permit No. 3804, 1961 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

Photo 3 of 3 : UCIP_SP_2018_23463_40620.jpg



View of gas line markers approximately 900 feet away.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.55	Rating **	M	Issue No.	42
LM End	0.55	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.142565 °	39.142565 °	
			-121.841600 °	-121.841600 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23227 DS_ID:21348 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Need to contact PG&E to confirm that crossing was completely removed. FIELD_STRUCT_DESC: 16-inch steel natural gas pipeline through the levee, 2.5 feet below the crown. (Plans to remove an existing 16-inch pipe and install an 8-inch natural gas pipe to existing pipe within the 10-foot landside (LS) limits of the levee authorized under Permit No. 15936, 1992 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

No Photos

LM Start	0.55	Rating **	M	Issue No.	43
LM End	0.55	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.142565 °	39.142565 °	
			-121.841600 °	-121.841600 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23228 DS_ID:21349 EP_NO: 4994 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Need to contact PG&E to determine fate of crossing--active or inactive. FIELD_STRUCT_DESC: 12-inch coated steel high-pressure natural gas pipeline through the levee, 2.5 feet below the crown. Concrete cutoff wall around the pipe between the center of the levee and the waterside (WS) shoulder. Marker signs at each shoulder. (Plans to install, use, and maintain a 12-inch gas line authorized under Permit No. 4994, 1965 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.55	Rating **	M	Issue No.	44
LM End	0.55	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.142565 °	39.142565 °
				-121.841600 °	-121.841600 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23384 DS_ID:21415 EP_NO: 15936 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No markers visible on levee slope or levee toe to indicate line crosses levee. Need to contact PG&E to confirm location through levee. Also need to confirm the emergency contact person for this crossing. FIELD_STRUCT_DESC: 8-inch steel natural gas pipeline through the levee, 2.5 feet below the crown. Gas line markers on the landside (LS). (Plans to remove an existing 16-inch pipe and install an 8-inch natural gas pipe to existing pipe within the 10-foot LS limits of the levee authorized under Permit No. 15936, 1992 - Pacific Gas and Electric Company [PG&E]). FS Date: 10/21/2013					

Photo 1 of 3 : UCIP_SP_2018_23384_40249.jpg



View of markers on the east side of S. Tarke Road.

LM Start	0.55	Rating **	M	Issue No.	44 (cont)
LM End	0.55	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23384_40247.jpg



View of markers on the west side of S. Tarke Road.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.55	Rating **	M	Issue No.	44 (cont)	
LM End	0.55	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.142565 °	39.142565 °	
				-121.841600 °	-121.841600 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23384 DS_ID:21415 EP_NO: 15936 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No markers visible on levee slope or levee toe to indicate line crosses levee. Need to contact PG&E to confirm location through levee. Also need to confirm the emergency contact person for this crossing. FIELD_STRUCT_DESC: 8-inch steel natural gas pipeline through the levee, 2.5 feet below the crown. Gas line markers on the landside (LS). (Plans to remove an existing 16-inch pipe and install an 8-inch natural gas pipe to existing pipe within the 10-foot LS limits of the levee authorized under Permit No. 15936, 1992 - Pacific Gas and Electric Company [PG&E]). FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23384_40248.jpg



delete

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.57	Rating **	M	Issue No.	45	
LM End	0.57	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.142682 °	39.142682 °	
				-121.841913 °	-121.841913 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23503						
DS_ID:21351						
EP_NO: 3686						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to find the gate valve on landward side. Walkway on waterward side in bad shape. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0300 for 18 inch pipe. Pipe on LS is 10 inch not 18 inch. SEE UCIP DS_ID 21350 for details pertaining to 18 inch pipe.						
FIELD_STRUCT_DESC: 10-inch irrigation discharge pipe of an unknown material through the levee, 14.8 feet below the crown. Electrical conduit through the levee, 1 foot below the crown. Pump on a pile structure in the stream. Service pole with meter and control panel at the landside (LS) toe. Slide gate with walkway on the waterside (WS) end. Gate valve on the LS end, not found during 10/21/2013 pipe inventory. Rock revetment on the WS slope. (Plans for removal of a pump on the LS and installation of a pump and two concrete piers on the WS authorized under Permit No. 3686, 1961 - Gerald A. Frye). [Additional Reference(s): DWR Levee Log, 2007].						
FS Date: 10/21/2013						

LM Start	0.57	Rating **	M	Issue No.	45 (cont)
LM End	0.57	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23503_40784.jpg



View of levee crown looking upstream from crossing.

Photo 2 of 3 : UCIP_SP_2018_23503_40780.jpg



View of levee crown looking downstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.57	Rating **	M	Issue No.	45 (cont)	
LM End	0.57	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.142682 °	39.142682 °	
				-121.841913 °	-121.841913 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23503 DS_ID:21351 EP_NO: 3686 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to find the gate valve on landward side. Walkway on waterward side in bad shape. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0300 for 18 inch pipe. Pipe on LS is 10 inch not 18 inch. SEE UCIP DS_ID 21350 for details pertaining to 18 inch pipe. FIELD_STRUCT_DESC: 10-inch irrigation discharge pipe of an unknown material through the levee, 14.8 feet below the crown. Electrical conduit through the levee, 1 foot below the crown. Pump on a pile structure in the stream. Service pole with meter and control panel at the landside (LS) toe. Slide gate with walkway on the waterside (WS) end. Gate valve on the LS end, not found during 10/21/2013 pipe inventory. Rock revetment on the WS slope. (Plans for removal of a pump on the LS and installation of a pump and two concrete piers on the WS authorized under Permit No. 3686, 1961 - Gerald A. Frye). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23503_40785.jpg



View of waterward side--dense vegetation along slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.63	Rating **	M	Issue No.	46
LM End	0.63	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.143380 °	39.143380 °
				-121.842606 °	-121.842606 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23467
DS_ID:21354
EP_NO: 14802
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Need to contact owner to determine status of crossing. Need date of last inspection and confirmation that crossing is still in operable condition. Markers found about 159 feet upstream of coordinates at the crossing of the ramp and S. Tarke Road (39.142684, -121.842685).
FIELD_STRUCT_DESC: 4-inch steel natural gas pipeline through the levee, 2.5 feet below the crown. Aluminum pipe marker on the landside (LS) slope. Emergency contact information for Pacific Gas and Electric Company (PG&E): (800) 344-4749? or 4742? or (916) 742-3251. (Plans to replace an existing 3-inch natural gas main through the levee with a new 4-inch steel pipe authorized under Permit No. 14802, 1987 - PG&E). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	0.63	Rating **	M	Issue No.	46 (cont)
LM End	0.63	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23467_40643.jpg



Underground Service Alert (USA) flag located at the end of Hwy 20 confirming gas line goes through.

Photo 2 of 3 : UCIP_SP_2018_23467_40641.jpg



Additional appurtenances for gas line located at landward side near S. Tarke Rd.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.63	Rating **	M	Issue No.	46 (cont)	
LM End	0.63	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.143380 °	39.143380 °	
				-121.842606 °	-121.842606 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23467 DS_ID:21354 EP_NO: 14802 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to contact owner to determine status of crossing. Need date of last inspection and confirmation that crossing is still in operable condition. Markers found about 159 feet upstream of coordinates at the crossing of the ramp and S. Tarke Road (39.142684, -121.842685). FIELD_STRUCT_DESC: 4-inch steel natural gas pipeline through the levee, 2.5 feet below the crown. Aluminum pipe marker on the landside (LS) slope. Emergency contact information for Pacific Gas and Electric Company (PG&E): (800) 344-4749? or 4742? or (916) 742-3251. (Plans to replace an existing 3-inch natural gas main through the levee with a new 4-inch steel pipe authorized under Permit No. 14802, 1987 - PG&E). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23467_40640.jpg



Close-up of the additional appurtenances for gas line located landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.70	Rating **	M	Issue No.	47
LM End	0.70	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.144369 °	39.144369 °
				-121.842778 °	-121.842778 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23526 DS_ID:21355 EP_NO: 9961 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense burrow activity present on both waterward side and landward side. Recommend addressing burrow activity at this location. Also recommend having owner clear vegetation blocking access along walkway. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_290. FIELD_STRUCT_DESC: 10-inch (not 12-inch as referenced in the permit) steel irrigation discharge pipe through the levee, 5.4 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. 24-inch concrete standpipe at the LS toe. Walkway to the pump on a pile structure in the stream. (Retention of a 12-inch steel irrigation pipe through the levee, 5.4 feet below the crown, a walkway to the pump on a pile structure in the stream, and a siphon breaker in a CMP riser on the landward slope authorized under Automatic Board Order (ABO) issued as Permit No. 9961, 1974 - Louis Tarke, Trustee). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

LM Start	0.70	Rating **	M	Issue No.	47 (cont)
LM End	0.70	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23526_40942.jpg



View of levee crown and waterward berm looking downstream from crossing.

Photo 2 of 3 : UCIP_SP_2018_23526_40941.jpg



View of standpipe and CMP riser located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

Reclamation District No. 0070 Meridian

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.76	Rating **	A/W	Issue No.	36	
LM End	0.76	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			39.145240 °		39.145240 °
				-121.842650 °		-121.842650 °
DWR ID	DWR_RD0070_01_f_2017_36					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:154						
Site Designation:RD 70-03						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes:						

LM Start	0.76	Rating **	A/W	Issue No.	36 (cont)
LM End	0.76	Issue Type +	Ma	Location *	

Photo 1 of 3 : LEVAL_SP_2018_154_1686.jpg



Photo 2 of 3 : LEVAL_SP_2018_154_1687.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.76	Rating **	A/W	Issue No.	36 (cont)	
LM End	0.76	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.145240 °	39.145240 °	
				-121.842650 °	-121.842650 °	
DWR ID	DWR_RD0070_01_f_2017_36					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:154						
Site Designation:RD 70-03						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes:						

Photo 3 of 3 : LEVAL_SP_2018_154_1688.jpg



LM Start	1.77	Rating **	M	Issue No.	32
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.151282 °	39.151282 °
				-121.855818 °	-121.855818 °
DWR ID	DWR_RD0070_01_f_2016_32				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_29_32_20180305_00009.jpg



View of the rodent holes along the waterside slope.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.83	Rating **	M	Issue No.	48
LM End	1.83	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.151786 °	39.151786 °
				-121.856875 °	-121.856875 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23508
DS_ID:21336
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to find owner to determine if crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Evidence of high burrow activity on waterward side recommend addressing issue. This crossing is referenced as USACE_CESPK_MRD1_2012_p_0230 in the USACE's PI report for no USACE recommendation letter available -- correction pipe is 12-inch not 16-inch.
FIELD_STRUCT_DESC: 12-inch irrigation discharge pipe of an unknown material through the levee, 4 feet below the crown. Siphon breaker on the landside (LS) slope. 7-foot by 9-foot concrete distribution box at the LS toe. Service pole on the waterside (WS) slope. Pump on a concrete sump on the WS slope. Overhead power line crosses the levee. (Plans for the installation of a 12-inch steel irrigation pipe through the levee authorized under Permit No. 613, 1934 - Waldo M. Nall. Plans to retain a 12-inch pipe through the levee, 4 feet below the crown, pump, and siphon breaker authorized under Automatic Board Order (ABO) issued as Permit No. 9948, 1974 - Edward E. and Doris M. Nall). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	1.83	Rating **	M	Issue No.	48 (cont)
LM End	1.83	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23508_40821.jpg



View of levee crown looking upstream from crossing.

Photo 2 of 3 : UCIP_SP_2018_23508_40819.jpg



Dense burrow activity found on waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.83	Rating **	M	Issue No.	48 (cont)	
LM End	1.83	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.151786 °	39.151786 °	
				-121.856875 °	-121.856875 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23508 DS_ID:21336 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to find owner to determine if crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Evidence of high burrow activity on waterward side recommend addressing issue. This crossing is referenced as USACE_CESPK_MRD1_2012_p_0230 in the USACE's PI report for no USACE recommendation letter available -- correction pipe is 12-inch not 16-inch. FIELD_STRUCT_DESC: 12-inch irrigation discharge pipe of an unknown material through the levee, 4 feet below the crown. Siphon breaker on the landside (LS) slope. 7-foot by 9-foot concrete distribution box at the LS toe. Service pole on the waterside (WS) slope. Pump on a concrete sump on the WS slope. Overhead power line crosses the levee. (Plans for the installation of a 12-inch steel irrigation pipe through the levee authorized under Permit No. 613, 1934 - Waldo M. Nall. Plans to retain a 12-inch pipe through the levee, 4 feet below the crown, pump, and siphon breaker authorized under Automatic Board Order (ABO) issued as Permit No. 9948, 1974 - Edward E. and Doris M. Nall). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23508_40820.jpg



View of waterward side.

LM Start	2.74	Rating **	M	Issue No.	27
LM End	2.82	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.157741 °	39.158135 °
				-121.871588 °	-121.872979 °
DWR ID	DWR_RD0070_01_s_2016_27				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_29_27_20180305_00003.jpg



Concrete ditch at landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

Reclamation District No. 0070 Meridian

View of waterward slope.

Page 17 of 43

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.82	Rating **	M	Issue No.	49 (cont)
LM End	2.82	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.158151 °	39.158151 °
				-121.873005 °	-121.873005 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23530 DS_ID:21322 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Unable to determine if crossing exists need to coordinate with LMA to determine if more information is available about crossing. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0208 for concrete ditch lined within 15 feet of LS toe, no water present, and no USACE recommendation letter available. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, at an unknown depth. Cutoff wall around the pipe at the center of the levee. Slide gate on each end. Pump on the waterside (WS). Concrete distribution box on the landside (LS). [Additional Reference(s): USACE Sacramento O&M Manual 134, June 1953, (Station 142+70)]. FS Date: 10/21/2013					

Photo 3 of 3 : UCIP_SP_2018_23530_40971.jpg



Waterward side covered by vegetation.

LM Start	3.18	Rating **	A/W	Issue No.	37	
LM End	3.18	Issue Type +	Ob	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.157480 °	39.157480 °	
				-121.879250 °	-121.879250 °	
DWR ID	DWR_RD0070_01_f_2017_37					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:153						
Site Designation:RD 70-02						
Repair Type: Seepage (B)						
Rating:Serious						
Field Date:7/17/2017						
Notes:						

Photo 1 of 3 : LEVAL_SP_2018_153_1702.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.18	Rating **	A/W	Issue No.	37 (cont)	
LM End	3.18	Issue Type +	Ob	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.157480 °	39.157480 °	
				-121.879250 °	-121.879250 °	
DWR ID	DWR_RD0070_01_f_2017_37					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:153						
Site Designation:RD 70-02						
Repair Type: Seepage (B)						
Rating:Serious						
Field Date:7/17/2017						
Notes:						

LM Start	3.18	Rating **	A/W	Issue No.	37 (cont)
LM End	3.18	Issue Type +	Ob	Location *	

Photo 2 of 3 : LEVAL_SP_2018_153_1704.jpg



Photo 3 of 3 : LEVAL_SP_2018_153_1707.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.37	Rating **	M	Issue No.	50
LM End	3.37	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.156437 °	39.156437 °
				-121.882519 °	-121.882519 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23506
DS_ID:21361
EP_NO: 9944
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Burrow activity present on levee slopes. Multiple pipes found on landward side--are these pipes part of original crossing? This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0291--no USACE recommendation letter available.
FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 21.5 feet below the crown. Gate valve on the waterside (WS) end. Pipe discharges into a concrete box on the landside (LS). Rock revetment on the WS slope. (Retention of an 18-inch steel pipe through the levee, 21.5 feet below the crown, gate valve, and concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9944, 1974 - William J. and Marion D. Hankins). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	3.37	Rating **	M	Issue No.	50 (cont)
LM End	3.37	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23506_40806.jpg



View of waterward side slope and berm.

Photo 2 of 3 : UCIP_SP_2018_23506_40801.jpg



Recent burrow activity soil months next to holes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.37	Rating **	M	Issue No.	50 (cont)	
LM End	3.37	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.156437 °	39.156437 °	
				-121.882519 °	-121.882519 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23506 DS_ID:21361 EP_NO: 9944 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burrow activity present on levee slopes. Multiple pipes found on landward side--are these pipes part of original crossing? This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0291--no USACE recommendation letter available. FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 21.5 feet below the crown. Gate valve on the waterside (WS) end. Pipe discharges into a concrete box on the landside (LS). Rock revetment on the WS slope. (Retention of an 18-inch steel pipe through the levee, 21.5 feet below the crown, gate valve, and concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9944, 1974 - William J. and Marion D. Hankins). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23506_40807.jpg



U shaped concrete box located on waterward side contains pump, motor, stairs, and pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.63	Rating **	M	Issue No.	51
LM End	3.63	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.157330 °	39.157330 °
				-121.887113 °	-121.887113 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23510 DS_ID:21362 EP_NO: 9944 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No pump connection. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0183 no USACE recommendation letter available. FIELD_STRUCT_DESC: 18-inch irrigation discharge pipe of an unknown material through the levee, 19.5 feet below the crown. Slide gate on the waterside (WS) end. Pump on the WS. Concrete distribution box on the landside (LS) slope. (Retention of an 18-inch pipe through the levee, 19.5 feet below the crown, and appurtenances authorized under Automatic Board Order (ABO) issued as Permit No. 9944, 1974 - William J. and Marion D. Hankins). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 180+50)]. FS Date: 10/21/2013					

Photo 1 of 3 : UCIP_SP_2018_23510_40837.jpg



Concrete head wall and screw gate at waterward toe.

LM Start	3.63	Rating **	M	Issue No.	51 (cont)
LM End	3.63	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23510_40838.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.63	Rating **	M	Issue No.	51 (cont)	
LM End	3.63	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.157330 °		39.157330 °
				-121.887113 °		-121.887113 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23510 DS_ID:21362 EP_NO: 9944 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No pump connection. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0183 no USACE recommendation letter available. FIELD_STRUCT_DESC: 18-inch irrigation discharge pipe of an unknown material through the levee, 19.5 feet below the crown. Slide gate on the waterside (WS) end. Pump on the WS. Concrete distribution box on the landside (LS) slope. (Retention of an 18-inch pipe through the levee, 19.5 feet below the crown, and appurtenances authorized under Automatic Board Order (ABO) issued as Permit No. 9944, 1974 - William J. and Marion D. Hankins). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 180+50)]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23510_40836.jpg



View of appurtenances located on waterward side.

LM Start	3.72	Rating **	M	Issue No.	29
LM End	3.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.158183 °	39.158183 °
				-121.888397 °	-121.888397 °
DWR ID	DWR_RD0070_01_f_2016_29				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_29_29_20180305_00004.jpg



View of the ruts along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.15	Rating **	M	Issue No.	39
LM End	4.15	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.162757 °	39.162757 °
				-121.893805 °	-121.893805 °
DWR ID	DWR_RD0070_01_f_2017_39				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside toe.					

Photo 1 of 1 : SP_2018_RD0070_29_39_20180305_00020.jpg



View of the prunings along the Landside toe.

LM Start	4.30	Rating **	M	Issue No.	28
LM End	4.30	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.164240 °	39.164240 °
				-121.895758 °	-121.895758 °
DWR ID	DWR_RD0070_01_s_2018_28				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside toe.					

Photo 1 of 1 : SP_2018_RD0070_29_28_20180402_00075.jpg



View of the prunings along the landside toe.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.55	Rating **	M	Issue No.	52
LM End	4.55	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.166859 °	39.166859 °
				-121.898846 °	-121.898846 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23515 DS_ID:21364 EP_NO: 9954 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Power pole down on waterward side. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0147. FIELD_STRUCT_DESC: 18-inch (not 24-inch as referenced in the permit) steel irrigation discharge pipe through the levee, 18 feet below the crown. Pipe crosses the levee at a 45 degree angle. Slide gate in a 5-foot by 5-foot concrete box at the waterside (WS) toe. Pump in a pump house on the WS, not found. Discharge box at the landside (LS) toe. Power pole at the WS toe. (Retention of a 24-inch steel pipe through the levee, 18 feet below the crown, pump, slide gate, and discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9954, 1974 - Parker A. Reische). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

LM Start	4.55	Rating **	M	Issue No.	52 (cont)
LM End	4.55	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23515_40867.jpg



View of waterward slope.

Photo 2 of 3 : UCIP_SP_2018_23515_40868.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.55	Rating **	M	Issue No.	52 (cont)	
LM End	4.55	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.166859 °	39.166859 °	
				-121.898846 °	-121.898846 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23515 DS_ID:21364 EP_NO: 9954 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Power pole down on waterward side. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0147. FIELD_STRUCT_DESC: 18-inch (not 24-inch as referenced in the permit) steel irrigation discharge pipe through the levee, 18 feet below the crown. Pipe crosses the levee at a 45 degree angle. Slide gate in a 5-foot by 5-foot concrete box at the waterside (WS) toe. Pump in a pump house on the WS, not found. Discharge box at the landside (LS) toe. Power pole at the WS toe. (Retention of a 24-inch steel pipe through the levee, 18 feet below the crown, pump, slide gate, and discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9954, 1974 - Parker A. Reische). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23515_40869.jpg



View of concrete box located on waterward side, photo 2 of 2.

LM Start	4.57	Rating **	C	Issue No.	34
LM End	4.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.167168 °	39.167168 °
				-121.899102 °	-121.899102 °
DWR ID	DWR_RD0070_01_s_2015_34				
Comment Code					
PR : Prunings					
Inspector Comment					
The prunings was removed from landside toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.59	Rating **	M	Issue No.	53
LM End	4.59	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.167406 °	39.167406 °
				-121.899277 °	-121.899277 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23516 DS_ID:21339 EP_NO: 9951 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0144. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee, 16.3 feet below the crown. Pipe crosses the levee at a 45 degree angle. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Gate valve on the waterside (WS) end. Pipe discharges into a concrete discharge box. (Plans to retain a 10-inch steel pipe through the levee, 16.3 feet below the crown, a gate valve, a siphon breaker in a CMP riser, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9951, 1974 - Frank and Mischa Pirtle). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013					

LM Start	4.59	Rating **	M	Issue No.	53 (cont)
LM End	4.59	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23516_40873.jpg



View of pipe located on waterward side.

Photo 2 of 3 : UCIP_SP_2018_23516_40872.jpg



View of pipe on landward side inside concrete distribution box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.59	Rating **	M	Issue No.	53 (cont)	
LM End	4.59	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.167406 °	39.167406 °	
				-121.899277 °	-121.899277 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23516 DS_ID:21339 EP_NO: 9951 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0144. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee, 16.3 feet below the crown. Pipe crosses the levee at a 45 degree angle. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Gate valve on the waterside (WS) end. Pipe discharges into a concrete discharge box. (Plans to retain a 10-inch steel pipe through the levee, 16.3 feet below the crown, a gate valve, a siphon breaker in a CMP riser, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9951, 1974 - Frank and Mischa Pirtle). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23516_40874.jpg



Concrete distribution box located at landward toe.

LM Start	4.65	Rating **	M	Issue No.	30
LM End	4.65	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.168110 °	39.168110 °
				-121.899910 °	-121.899910 °
DWR ID	DWR_RD0070_01_f_2016_30				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

Photo 1 of 2 : SP_2018_RD0070_29_30_20180305_00005.jpg



View of the prunings along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.65	Rating **	M	Issue No.	30 (cont)	
LM End	4.65	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Encroachments			39.168110 °	39.168110 °	
				-121.899910 °	-121.899910 °	
DWR ID	DWR_RD0070_01_f_2016_30					
Comment Code						
PR : Prunings						
Inspector Comment						
Remove the prunings from the landside slope.						

Photo 2 of 2 : SP_2018_RD0070_29_30_20180305_00006.jpg



View of the prunings along the landside toe.

LM Start	4.71	Rating **	M	Issue No.	54	
LM End	4.71	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.168832 °	39.168832 °	
				-121.900436 °	-121.900436 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23517 DS_ID:21340 EP_NO: 9954 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burrow activity present on waterward slope. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0134. FIELD_STRUCT_DESC: 24-inch corrugated metal irrigation discharge pipe through the levee, 19 feet below the crown. Slide gate on the waterside (WS). Concrete distribution box at the landside (LS) toe. (Retention of a 24-inch corrugated metal pipe (CMP) through the levee, 19 feet below the crown, a slide gate, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9954, 1974 - Parker A. Reische). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 1 of 3 : UCIP_SP_2018_23517_40883.jpg



delete

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.71	Rating **	M	Issue No.	54 (cont)	
LM End	4.71	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.168832 °	39.168832 °	
				-121.900436 °	-121.900436 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23517 DS_ID:21340 EP_NO: 9954 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burrow activity present on waterward slope. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0134. FIELD_STRUCT_DESC: 24-inch corrugated metal irrigation discharge pipe through the levee, 19 feet below the crown. Slide gate on the waterside (WS). Concrete distribution box at the landside (LS) toe. (Retention of a 24-inch corrugated metal pipe (CMP) through the levee, 19 feet below the crown, a slide gate, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9954, 1974 - Parker A. Reische). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

LM Start	4.71	Rating **	M	Issue No.	54 (cont)
LM End	4.71	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23517_40877.jpg



View of pipe located on waterward side.

Photo 3 of 3 : UCIP_SP_2018_23517_40882.jpg



View of slide gate on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.99	Rating **	M	Issue No.	55
LM End	4.99	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.172334 °	39.172334 °
				-121.902998 °	-121.902998 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23518

DS_ID:21338

EP_NO: 9940

Repair Type: Non-Urgent

Crossing Status: Found

UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0125.

FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 19 feet below the crown. Cutoff wall around the pipe at the center of the levee. Slide gate in a concrete distribution box on the landside (LS). Pump on the waterside (WS). Pipe discharges into a concrete box on the LS. (Retention of an 18-inch steel pipe through the levee, 19 feet below the crown, a pump, a slide gate in a concrete distribution box, and a concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9940, 1974 - Pearl Clark, et al.). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 251+30)].

FS Date: 10/21/2013

LM Start	4.99	Rating **	M	Issue No.	55 (cont)
LM End	4.99	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23518_40886.jpg



View of waterward side--pipe and concrete distribution box.

Photo 2 of 3 : UCIP_SP_2018_23518_40887.jpg



View of waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.99	Rating **	M	Issue No.	55 (cont)							
LM End	4.99	Issue Type +	En	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP Field Study		39.172334 °	39.172334 °								
			-121.902998 °	-121.902998 °								
DWR ID												
Comment Code												
Inspector Comment												
FS_ID:23518 DS_ID:21338 EP_NO: 9940 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0125. FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 19 feet below the crown. Cutoff wall around the pipe at the center of the levee. Slide gate in a concrete distribution box on the landside (LS). Pump on the waterside (WS). Pipe discharges into a concrete box on the LS. (Retention of an 18-inch steel pipe through the levee, 19 feet below the crown, a pump, a slide gate in a concrete distribution box, and a concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9940, 1974 - Pearl Clark, et al.). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 251+30)]. FS Date: 10/21/2013												

Photo 3 of 3 : UCIP_SP_2018_23518_40890.jpg



Screw gate located inside concrete distribution box located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	5.41	Rating **	M	Issue No.	56	
LM End	5.41	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.176780 °	39.176780 °	
				-121.908025 °	-121.908025 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23519 DS_ID:21357 EP_NO: 9957 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burrow activity on slopes -- recommend addressing issue. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0110. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 5.5 feet below the crown. Pump on the waterside (WS) slope. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Pipe discharges into a concrete box at the LS toe. Service pole at the LS toe. (Plans to retain a 12-inch steel pipe through the levee, 5.5 feet below the crown, a siphon breaker in a CMP riser, a pump, and a concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9957, 1974 - James E. and Mattie Smith). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 1 of 3 : UCIP_SP_2018_23519_40896.jpg



View of waterward side--pump, pipe, and walkway.

LM Start	5.41	Rating **	M	Issue No.	56 (cont)
LM End	5.41	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23519_40898.jpg



Pipe and electrical conduit exposed on levee berm.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	5.41	Rating **	M	Issue No.	56 (cont)	
LM End	5.41	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.176780 °	39.176780 °	
				-121.908025 °	-121.908025 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23519 DS_ID:21357 EP_NO: 9957 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Burrow activity on slopes -- recommend addressing issue. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0110. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 5.5 feet below the crown. Pump on the waterside (WS) slope. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Pipe discharges into a concrete box at the LS toe. Service pole at the LS toe. (Plans to retain a 12-inch steel pipe through the levee, 5.5 feet below the crown, a siphon breaker in a CMP riser, a pump, and a concrete box authorized under Automatic Board Order (ABO) issued as Permit No. 9957, 1974 - James E. and Mattie Smith). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23519_40897.jpg



View of landward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.12	Rating **	M	Issue No.	57
LM End	6.12	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.186652 °	39.186652 °
				-121.910549 °	-121.910549 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23479
DS_ID:21360
EP_NO: 4867
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Utility marker contact information includes Contact prior to Excavation call 1-800-227-2600 or Emergency Contact 1-800-811-4111. Need to contact owner to determine status of crossing. Need date of last inspection and confirmation that crossing is still in operable condition.
FIELD_STRUCT_DESC: 6.5-inch coated steel natural gas pipeline through the levee, 4 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Rock revetment on the waterside (WS) slope. (Plans for installing a gas line through the levee authorized under Permit No. 4867, 1965 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	6.12	Rating **	M	Issue No.	57 (cont)
LM End	6.12	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23479_40724.jpg



View of landward side.

Photo 2 of 3 : UCIP_SP_2018_23479_40723.jpg



Pipeline marker on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.12	Rating **	M	Issue No.	57 (cont)	
LM End	6.12	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.186652 °	39.186652 °	
				-121.910549 °	-121.910549 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23479						
DS_ID:21360						
EP_NO: 4867						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Utility marker contact information includes Contact prior to Excavation call 1-800-227-2600 or Emergency Contact 1-800-811-4111. Need to contact owner to determine status of crossing. Need date of last inspection and confirmation that crossing is still in operable condition.						
FIELD_STRUCT_DESC: 6.5-inch coated steel natural gas pipeline through the levee, 4 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Rock revetment on the waterside (WS) slope. (Plans for installing a gas line through the levee authorized under Permit No. 4867, 1965 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007].						
FS Date: 10/21/2013						

Photo 3 of 3 : UCIP_SP_2018_23479_40722.jpg



View of waterward side.

LM Start	6.18	Rating **	M	Issue No.	6
LM End	6.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.187481 °	39.187481 °
				-121.910852 °	-121.910852 °
DWR ID	DWR_RD0070_01_s_2012_6				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 2 : SP_2018_RD0070_29_6_20180305_00001.jpg



View of vehicle erosion along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.18	Rating **	M	Issue No.	6 (cont)	
LM End	6.18	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			39.187481 °		39.187481 °
				-121.910852 °		-121.910852 °
DWR ID	DWR_RD0070_01_s_2012_6					
Comment Code						
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.						
Inspector Comment						

Photo 2 of 2 : SP_2018_RD0070_29_6_20180305_00002.jpg



View of the vehicle erosion along the waterside slope.

LM Start	6.44	Rating **	M	Issue No.	35
LM End	6.44	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.190897 °	39.190897 °
				-121.912713 °	-121.912713 °
DWR ID	DWR_RD0070_01_s_2018_35				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2018_RD0070_29_35_20180403_00076.jpg



View of the rodent holes along the landside slope.

LM Start	6.57	Rating **	U	Issue No.	40
LM End	6.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.192283 °	39.192283 °
				-121.914388 °	-121.914388 °
DWR ID	DWR_RD0070_01_s_2018_40				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2018_RD0070_29_40_20180403_00077.jpg



View of rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.58	Rating **	M	Issue No.	58	
LM End	6.58	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.192336 °	39.192336 °	
				-121.914637 °	-121.914637 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46422 DS_ID:21341 EP_NO: 9960 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 07/28/2015 Pipe appears still appears abandoned. Priority was downgraded from Urgent to Non-Urgent due to the inactivity. Need to contact owner to confirm status and future use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements.10/21/2013 Hole present on pipe on waterward side. This crossing was determined urgent due to hole on pipe-no signs leaks present on waterward or landward slopes. Unable to find if crossing is being used. Need to contact owner to determine crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0069. FIELD_STRUCT_DESC: 12-inch steel pipe of an unknown purpose through the levee, 6.2 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Retention of a 12-inch steel pipe through the levee, 6.2 feet below the crown, a siphon breaker in a CMP riser, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9960, 1974 - Richard L. and Mildred E. Tarke). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 332+72)]. FS Date: 7/28/2015 3:30:00 PM						

Photo 1 of 3 : UCIP_SP_2018_46422_74619.jpg



Overview of levee crown at crossing. No change from last inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.58	Rating **	M	Issue No.	58 (cont)	
LM End	6.58	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.192336 °	39.192336 °	
				-121.914637 °	-121.914637 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46422 DS_ID:21341 EP_NO: 9960 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 07/28/2015 Pipe appears still appears abandoned. Priority was downgraded from Urgent to Non-Urgent due to the inactivity. Need to contact owner to confirm status and future use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements.10/21/2013 Hole present on pipe on waterward side. This crossing was determined urgent due to hole on pipe-no signs leaks present on waterward or landward slopes. Unable to find if crossing is being used. Need to contact owner to determine crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0069. FIELD_STRUCT_DESC: 12-inch steel pipe of an unknown purpose through the levee, 6.2 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Retention of a 12-inch steel pipe through the levee, 6.2 feet below the crown, a siphon breaker in a CMP riser, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9960, 1974 - Richard L. and Mildred E. Tarke). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 332+72)]. FS Date: 7/28/2015 3:30:00 PM						

Photo 2 of 3 : UCIP_SP_2018_46422_40914.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.58	Rating **	M	Issue No.	58 (cont)	
LM End	6.58	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.192336 °	39.192336 °	
				-121.914637 °	-121.914637 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46422 DS_ID:21341 EP_NO: 9960 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 07/28/2015 Pipe appears still appears abandoned. Priority was downgraded from Urgent to Non-Urgent due to the inactivity. Need to contact owner to confirm status and future use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements.10/21/2013 Hole present on pipe on waterward side. This crossing was determined urgent due to hole on pipe-no signs leaks present on waterward or landward slopes. Unable to find if crossing is being used. Need to contact owner to determine crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0069. FIELD_STRUCT_DESC: 12-inch steel pipe of an unknown purpose through the levee, 6.2 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) slope. Service pole on the LS shoulder. Concrete distribution box at the LS toe. (Retention of a 12-inch steel pipe through the levee, 6.2 feet below the crown, a siphon breaker in a CMP riser, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9960, 1974 - Richard L. and Mildred E. Tarke). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 332+72)]. FS Date: 7/28/2015 3:30:00 PM						

Photo 3 of 3 : UCIP_SP_2018_46422_40913.jpg



View of waterward slope and pipe at levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.74	Rating **	M	Issue No.	59
LM End	6.74	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.194042 °	39.194042 °	
			-121.916630 °	-121.916630 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:49188
DS_ID:21342
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: 06/21/2016 This crossing has been modified DWR levee log indicates 12-inch pipe not a 8-inch pipe, unable to determine if pipe goes through levee. This crossing appears to be an irrigation line. Need to find owner to clarify pipe use, determine whether pipe goes through levee, and determine the fate of the original 12-inch pipe through the levee. 10/21/2013 Unable to determine if this is an irrigation pipe or groundwater pipe. This crossing is referenced in the USACE Periodic Inspection as item
USACE_CESPK_MRD1_2012_p_0062--no permit available.
FIELD_STRUCT_DESC: 8-inch (not 12-inch as found in desk study) pipe of an unknown material or purpose through the levee, at an unknown depth. Pump and service pole at the landside (LS) toe.
[Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/21/2013

LM Start	6.74	Rating **	M	Issue No.	59 (cont)
LM End	6.74	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2018_49188_40922.jpg



View of landward side.

Photo 2 of 2 : UCIP_SP_2018_49188_40921.jpg



Pump system and pipe on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.54	Rating **	M	Issue No.	38
LM End	7.54	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.196665 °	39.196665 °
				-121.929558 °	-121.929558 °
DWR ID	DWR_RD0070_01_f_2017_38				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree limbs from the landside toe.					

Photo 1 of 1 : SP_2018_RD0070_29_38_20180305_00019.jpg



View of the tree limbs along the landside toe.

LM Start	7.80	Rating **	M	Issue No.	60	
LM End	7.80	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.195148 °	39.195148 °	
				-121.933849 °	-121.933849 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23529 DS_ID:21345 EP_NO: 9942 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0005. FIELD_STRUCT_DESC: 24-inch corrugated metal irrigation discharge pipe through the levee, 16.5 feet below the crown. Incline pump on the waterside (WS). Slide gate in a corrugated metal pipe (CMP) riser on the WS slope. Pipe discharges into a concrete box at the landside (LS) toe. Service pole on the LS. (Retention of a 24-inch CMP through the levee, 16.5 feet below the crown, a slant pump, a slide gate in a CMP riser, a box, and a service pole authorized under Automatic Board Order (ABO) issued as Permit No. 9942, 1974 - R. W. and H. Evelyn Draper). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 330+00)]. FS Date: 10/21/2013						

Photo 1 of 3 : UCIP_SP_2018_23529_40964.jpg



View of waterward slope.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Reclamation District No. 0070 Meridian

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Reclamation District No. 0070 Meridian

Waterway			Bank	Unit Miles
Unit No. 02 Sacramento River			Left	15.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/15/2018 - 3/15/2018			
DWR Inspector	Bob Duffey			
Accompanied By	Andy Duffey RD 70			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.05	Rating **	U	Issue No.	79
LM End	0.05	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.193396 °	39.193396 °
				-121.935434 °	-121.935434 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:52618
DS_ID:21382
EP_NO: 12707
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 05/16/2018 2-foot round depression on waterward side found 4.5' from levee crown (Marty Rd). 14'x8'x3' excavation found on waterside slope to expose 14"-pipe. Evidence of internal erosion found at the bottom of excavation toward the pump. Cracks in asphalt pavement on levee crown (DWR UCIP - O.Yakimov)
11/03/2017 Crossing failed on WS and section of the levee was exposed to determine the extend of pipe damage by owner. Pipe is an up and over crossing. Crossing has been upgraded from Non-Urgent to Urgent due to pipe failure and exposed section of the levee visible on WS. (DWR UCIP - O. Magana)10/22/2013 Burrow activity noticed at this location. Crossing appurtenances have been modified. No 36-inch concrete distribution stand pipe present instead there is a concrete distribution box located at the landward toe. Also siphon breaker housing unit damage. Will need to contact owner. Need to obtain maintenance records and clarify modifications made at to crossing. Recommend having owner clear vegetation on waterward side. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0018.
FIELD_STRUCT_DESC: 14-inch coated steel irrigation discharge pipe through the levee, 3 feet below the crown. Steel cutoff wall around the pipe at the center of the levee. Pump on a metal platform (not timber as noted in the desk study) on the waterside (WS). Siphon breaker on the apex of the pipe at the WS shoulder. 36-inch concrete standpipe at the landside (LS) toe, not found during October 2013 inspection. Service pole at the LS toe. Rock revetment on the WS slope. (Plans to install a 30-kilowatt [40-horsepower] pump on the riverbank with a 14-inch steel discharge pipe through the levee authorized under Permit No. 12707, 1979 - Roger C. Wilber, Butte Creek Farms). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 5/16/2018

Photo 1 of 3 : UCIP_SP_2018_52618_42061.jpg



View of waterward side--siphon breaker housing unit, pipe daylight, pump, and plateform.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.05	Rating **	U	Issue No.	79 (cont)
LM End	0.05	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.193396 °	39.193396 °
				-121.935434 °	-121.935434 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:52618
 DS_ID:21382
 EP_NO: 12707
 Repair Type: Urgent
 Crossing Status: Found
 UCIP Comments: 05/16/2018 2-foot round depression on waterward side found 4.5' from levee crown (Marty Rd). 14'x8'x3' excavation found on waterside slope to expose 14"-pipe. Evidence of internal erosion found at the bottom of excavation toward the pump. Cracks in asphalt pavement on levee crown (DWR UCIP - O.Yakimov)
 11/03/2017 Crossing failed on WS and section of the levee was exposed to determine the extend of pipe damage by owner. Pipe is an up and over crossing. Crossing has been upgraded from Non-Urgent to Urgent due to pipe failure and exposed section of the levee visible on WS. (DWR UCIP - O. Magana)10/22/2013 Burrow activity noticed at this location. Crossing appurtenances have been modified. No 36-inch concrete distribution stand pipe present instead there is a concrete distribution box located at the landward toe. Also siphon breaker housing unit damage. Will need to contact owner. Need to obtain maintenance records and clarify modifications made at to crossing. Recommend having owner clear vegetation on waterward side. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0018.
 FIELD_STRUCT_DESC: 14-inch coated steel irrigation discharge pipe through the levee, 3 feet below the crown. Steel cutoff wall around the pipe at the center of the levee. Pump on a metal platform (not timber as noted in the desk study) on the waterside (WS). Siphon breaker on the apex of the pipe at the WS shoulder. 36-inch concrete standpipe at the landside (LS) toe, not found during October 2013 inspection. Service pole at the LS toe. Rock revetment on the WS slope. (Plans to install a 30-kilowatt [40-horsepower] pump on the riverbank with a 14-inch steel discharge pipe through the levee authorized under Permit No. 12707, 1979 - Roger C. Wilber, Butte Creek Farms). [Additional Reference(s): DWR Levee Log, 2007].
 FS Date: 5/16/2018

Photo 2 of 3 : UCIP_SP_2018_52618_42060.jpg



View of pump on waterward side.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.05	Rating **	U	Issue No.	79 (cont)
LM End	0.05	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.193396 °	39.193396 °
				-121.935434 °	-121.935434 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:52618
DS_ID:21382
EP_NO: 12707
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 05/16/2018 2-foot round depression on waterward side found 4.5' from levee crown (Marty Rd). 14'x8'x3' excavation found on waterside slope to expose 14"-pipe. Evidence of internal erosion found at the bottom of excavation toward the pump. Cracks in asphalt pavement on levee crown (DWR UCIP - O.Yakimov)
11/03/2017 Crossing failed on WS and section of the levee was exposed to determine the extend of pipe damage by owner. Pipe is an up and over crossing. Crossing has been upgraded from Non-Urgent to Urgent due to pipe failure and exposed section of the levee visible on WS. (DWR UCIP - O. Magana)10/22/2013 Burrow activity noticed at this location. Crossing appurtenances have been modified. No 36-inch concrete distribution stand pipe present instead there is a concrete distribution box located at the landward toe. Also siphon breaker housing unit damage. Will need to contact owner. Need to obtain maintenance records and clarify modifications made at to crossing. Recommend having owner clear vegetation on waterward side. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0018.
FIELD_STRUCT_DESC: 14-inch coated steel irrigation discharge pipe through the levee, 3 feet below the crown. Steel cutoff wall around the pipe at the center of the levee. Pump on a metal platform (not timber as noted in the desk study) on the waterside (WS). Siphon breaker on the apex of the pipe at the WS shoulder. 36-inch concrete standpipe at the landside (LS) toe, not found during October 2013 inspection. Service pole at the LS toe. Rock revetment on the WS slope. (Plans to install a 30-kilowatt [40-horsepower] pump on the riverbank with a 14-inch steel discharge pipe through the levee authorized under Permit No. 12707, 1979 - Roger C. Wilber, Butte Creek Farms). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 5/16/2018

Photo 3 of 3 : UCIP_SP_2018_52618_42062.jpg



View of levee slope on landward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	0.07	Rating **	A/W	Issue No.	74
LM End		Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		39.193083 °		
			-121.935258 °		
DWR ID	DWR_RD0070_02_f_2017_74				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:142					
Site Designation:LMA-22					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/7/2017					
Notes: Problematic site was not found. No erosion observed.					

No Photos

LM Start	1.04	Rating **	M	Issue No.	80
LM End	1.04	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.183211 °	39.183211 °	
			-121.943237 °	-121.943237 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:42923					
DS_ID:21412					
EP_NO: 1575					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Debris scattered on waterward side. Concrete structure on waterward side shows major cracks on the walls. Will need to notify owner. Need to obtain maintenance records to confirm integrity of pipe. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0075.					
FIELD_STRUCT_DESC: 20-inch steel irrigation discharge pipe through the levee, 17 feet below the crown. Pump and 10-inch slide gate in a pump house on the waterside (WS). Concrete collar at the WS toe. Power pole on the WS slope. Anchor on the landside (LS) slope. Rock revetment on the WS slope. (Plans for installing an irrigation pumping plant and a 20-inch discharge pipe through the levee authorized under Permit No. 1575, 1951 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].					
FS Date: 10/23/2013					

Photo 1 of 3 : UCIP_SP_2018_42923_42036.jpg



View of waterward side--appurtenances present pump house, concrete distribution box, screw gate, and power pole.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Reclamation District No. 0070 Meridian

Inside view of concrete distribution box located on waterward side.

Page 5 of 86

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.35	Rating **	M	Issue No.	81	
LM End	1.35	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.178895 °	39.178895 °	
				-121.943340 °	-121.943340 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23885 DS_ID:21365 EP_NO: 9973 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Cut to levee toe found on landward side. Unable to determine if crossing is being used. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0099. FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 18.8 feet below the crown. Slant pump on the waterside (WS). Slide gate on a gate structure on the WS. (Retention of an 18-inch steel pipe through the levee, 18.8 feet below the crown, and a slide gate authorized under Automatic Board Order (ABO) issued as Permit No. 9973, 1974 - Pearl V. Clark). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 399+34)]. FS Date: 10/22/2013						

LM Start	1.35	Rating **	M	Issue No.	81 (cont)
LM End	1.35	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23885_41814.jpg



View of waterward slope.

Photo 2 of 3 : UCIP_SP_2018_23885_41817.jpg



Overview of waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.35	Rating **	M	Issue No.	81 (cont)	
LM End	1.35	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.178895 °	39.178895 °	
				-121.943340 °	-121.943340 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23885 DS_ID:21365 EP_NO: 9973 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Cut to levee toe found on landward side. Unable to determine if crossing is being used. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0099. FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 18.8 feet below the crown. Slant pump on the waterside (WS). Slide gate on a gate structure on the WS. (Retention of an 18-inch steel pipe through the levee, 18.8 feet below the crown, and a slide gate authorized under Automatic Board Order (ABO) issued as Permit No. 9973, 1974 - Pearl V. Clark). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 399+34)]. FS Date: 10/22/2013						

Photo 3 of 3 : UCIP_SP_2018_23885_41815.jpg



Concrete structure located on waterward side with screw gate.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.87	Rating **	M	Issue No.	82
LM End	1.87	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.172778 °	39.172778 °	
			-121.937791 °	-121.937791 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:23888
DS_ID:21366
EP_NO: 9996
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need inside photo of the concrete distribution box located at the landward toe. Debris found on waterward slope (conduit running parallel to levee). This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0124.
FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 24 feet below the crown. Gate valve in a concrete U-shaped headwall on the waterside (WS) slope. Pump and switch house on the WS shoulder. Discharge box at the landside (LS) toe. (Retention of a 12-inch steel pipe through the levee, 24 feet below the crown, a pump, a gate valve, a switch house, and a discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9996, 1974 - Chas. F. and Nora M. Reische, et al.). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

LM Start	1.87	Rating **	M	Issue No.	82 (cont)
LM End	1.87	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23888_41819.jpg



View of levee crown and waterward side.

Photo 2 of 3 : UCIP_SP_2018_23888_41822.jpg



View of slope on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.87	Rating **	M	Issue No.	82 (cont)	
LM End	1.87	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.172778 °	39.172778 °	
				-121.937791 °	-121.937791 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23888 DS_ID:21366 EP_NO: 9996 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need inside photo of the concrete distribution box located at the landward toe. Debris found on waterward slope (conduit running parallel to levee). This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0124. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 24 feet below the crown. Gate valve in a concrete U-shaped headwall on the waterside (WS) slope. Pump and switch house on the WS shoulder. Discharge box at the landside (LS) toe. (Retention of a 12-inch steel pipe through the levee, 24 feet below the crown, a pump, a gate valve, a switch house, and a discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9996, 1974 - Chas. F. and Nora M. Reische, et al.). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013						

Photo 3 of 3 : UCIP_SP_2018_23888_41821.jpg



View of U-concrete headwall with positive closure device, photo 1 of 2.

LM Start	2.16	Rating **	M	Issue No.	1
LM End	2.32	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.168854 °	39.166503 °
				-121.936223 °	-121.935547 °
DWR ID	DWR_RD0070_02_s_2012_1				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_1_20180305_00001.jpg



Agricultural ditch along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.34	Rating **	U	Issue No.	83
LM End	2.34	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.166298 °	39.166298 °
				-121.935570 °	-121.935570 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:52551
DS_ID:21367
EP_NO: 1158
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 11/30/2017 According to DWR levee inspector, B. Duffey, the owner of the pipe did not operate pipe crossing in 2017. Owner is working with CVFPB at obtaining permit to replace pipe. (DWR UCIP - O. Magana)07/07/2016 Pipe was running during site visit. Pipe has failed internally on both the WS and LS. The scour hole on LS toe has progress and it is now about 6-feet wide by 6-feet long by 5-feet deep. Hole on WS is not visible but water is leaking underneath pipe. It appears from last inspection that the leak on the WS has also progressed. This section of the levee is known as N. Meridian Road (County Road). According to LMA representative, Andy Duffey, owner plans on submitting application for repair. Company submitting application is Davis Machine Shop contact is Thomas Davis 530-696-2576. Property owner is Steven Tarke. LMA representative contact number is 1-530-696-2569 (office) or 1-530-682-2996 (cell). Permit No. 1158 issued in 1946 lists owner as Wayne Hall. (DWR UCIP - omagana)07/28/2015 Pipe was running during site visit. Scour hole located at landward side (LS) toe is still present. New signs of stress on slope are visible on LS near concrete box. On the waterward side (WS) 2 leaks are present. The first leak is located at the pipe joint near the WS toe, the joint connection is leaking significantly. The second potential leak is near the pipe daylight on WS. Unable to confirm cause of leak but downstream seepage is present along pipe alignment. Seepage indicates that pipe may be leaking and causing internal erosion and void along pipe alignment. Recommend LMA superintendent notify owner to stop using crossing to avoid further damage to levee. Owner will need to coordinate with DWR Inspector and CVFPB to address leaky pipe per Title 23 requirements. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 4.1 feet below the crown. Pump in a pump house on a concrete stand on the waterside (WS) shoulder. Pipe discharges into a concrete box at the landside (LS) toe. Walkway to the pump house on the WS. (Plans to install a 6200 gallons per minute turbine pump in a steel pipe on the riverbank and a discharge pipe through the levee authorized under Permit No. 1158, 1946 - Wayne E. Hall). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 11/30/2017 2:28:33 PM

Photo 1 of 3 : UCIP_SP_2018_52551_74608.jpg



View of county road where pipe crosses.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.34	Rating **	U	Issue No.	83 (cont)
LM End	2.34	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.166298 °	39.166298 °	
			-121.935570 °	-121.935570 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:52551
DS_ID:21367
EP_NO: 1158
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 11/30/2017 According to DWR levee inspector, B. Duffey, the owner of the pipe did not operate pipe crossing in 2017. Owner is working with CVFPB at obtaining permit to replace pipe. (DWR UCIP - O. Magana)07/07/2016 Pipe was running during site visit. Pipe has failed internally on both the WS and LS. The scour hole on LS toe has progress and it is now about 6-feet wide by 6-feet long by 5-feet deep. Hole on WS is not visible but water is leaking underneath pipe. It appears from last inspection that the leak on the WS has also progressed. This section of the levee is known as N. Meridian Road (County Road). According to LMA representative, Andy Duffey, owner plans on submitting application for repair. Company submitting application is Davis Machine Shop contact is Thomas Davis 530-696-2576. Property owner is Steven Tarke. LMA representative contact number is 1-530-696-2569 (office) or 1-530-682-2996 (cell). Permit No. 1158 issued in 1946 lists owner as Wayne Hall. (DWR UCIP - omagana)07/28/2015 Pipe was running during site visit. Scour hole located at landward side (LS) toe is still present. New signs of stress on slope are visible on LS near concrete box. On the waterward side (WS) 2 leaks are present. The first leak is located at the pipe joint near the WS toe, the joint connection is leaking significantly. The second potential leak is near the pipe daylight on WS. Unable to confirm cause of leak but downstream seepage is present along pipe alignment. Seepage indicates that pipe may be leaking and causing internal erosion and void along pipe alignment. Recommend LMA superintendent notify owner to stop using crossing to avoid further damage to levee. Owner will need to coordinate with DWR Inspector and CVFPB to address leaky pipe per Title 23 requirements. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 4.1 feet below the crown. Pump in a pump house on a concrete stand on the waterside (WS) shoulder. Pipe discharges into a concrete box at the landside (LS) toe. Walkway to the pump house on the WS. (Plans to install a 6200 gallons per minute turbine pump in a steel pipe on the riverbank and a discharge pipe through the levee authorized under Permit No. 1158, 1946 - Wayne E. Hall). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 11/30/2017 2:28:33 PM

Photo 2 of 3 : UCIP_SP_2018_52551_74603.jpg



View of LS and county road (N. Meridian Road).

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.34	Rating **	U	Issue No.	83 (cont)
LM End	2.34	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.166298 °	39.166298 °
				-121.935570 °	-121.935570 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:52551
DS_ID:21367
EP_NO: 1158
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 11/30/2017 According to DWR levee inspector, B. Duffey, the owner of the pipe did not operate pipe crossing in 2017. Owner is working with CVFPB at obtaining permit to replace pipe. (DWR UCIP - O. Magana)07/07/2016 Pipe was running during site visit. Pipe has failed internally on both the WS and LS. The scour hole on LS toe has progress and it is now about 6-feet wide by 6-feet long by 5-feet deep. Hole on WS is not visible but water is leaking underneath pipe. It appears from last inspection that the leak on the WS has also progressed. This section of the levee is known as N. Meridian Road (County Road). According to LMA representative, Andy Duffey, owner plans on submitting application for repair. Company submitting application is Davis Machine Shop contact is Thomas Davis 530-696-2576. Property owner is Steven Tarke. LMA representative contact number is 1-530-696-2569 (office) or 1-530-682-2996 (cell). Permit No. 1158 issued in 1946 lists owner as Wayne Hall. (DWR UCIP - omagana)07/28/2015 Pipe was running during site visit. Scour hole located at landward side (LS) toe is still present. New signs of stress on slope are visible on LS near concrete box. On the waterward side (WS) 2 leaks are present. The first leak is located at the pipe joint near the WS toe, the joint connection is leaking significantly. The second potential leak is near the pipe daylight on WS. Unable to confirm cause of leak but downstream seepage is present along pipe alignment. Seepage indicates that pipe may be leaking and causing internal erosion and void along pipe alignment. Recommend LMA superintendent notify owner to stop using crossing to avoid further damage to levee. Owner will need to coordinate with DWR Inspector and CVFPB to address leaky pipe per Title 23 requirements. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 18-inch steel irrigation discharge pipe through the levee, 4.1 feet below the crown. Pump in a pump house on a concrete stand on the waterside (WS) shoulder. Pipe discharges into a concrete box at the landside (LS) toe. Walkway to the pump house on the WS. (Plans to install a 6200 gallons per minute turbine pump in a steel pipe on the riverbank and a discharge pipe through the levee authorized under Permit No. 1158, 1946 - Wayne E. Hall). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 11/30/2017 2:28:33 PM

Photo 3 of 3 : UCIP_SP_2018_52551_75306.jpg



Scour hole has progressed since 2015.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.40	Rating **	M	Issue No.	49
LM End	2.40	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.165462 °	39.165462 °
				-121.935244 °	-121.935244 °
DWR ID	DWR_RD0070_02_f_2016_49				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	2.61	Rating **	M	Issue No.	84
LM End	2.61	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.162424 °	39.162424 °
				-121.934201 °	-121.934201 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23891 DS_ID:21368 EP_NO: 9969 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Landward slope too steep--need photo of the inside of concrete distribution box. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0158. FIELD_STRUCT_DESC: 20-inch (not 24-inch as mentioned in the permit) steel irrigation discharge pipe through the levee, 27 feet below the crown. Corrugated metal cutoff wall around the pipe at the center of the levee. Pump and gate valve in a pump house on the waterside (WS) slope. Pipe discharges into a concrete box at the landside (LS) toe. (Retention of a 24-inch steel pipe through the levee, 27 feet below the crown, a pump and gate valve, a concrete box, and a service pole authorized under Automatic Board Order (ABO) No. 9969, 1974 - Edwin J. and Vivian L. Burrows). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 455+39), 24-inch listed]. FS Date: 10/22/2013					

Photo 1 of 3 : UCIP_SP_2018_23891_41835.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.61	Rating **	M	Issue No.	84 (cont)
LM End	2.61	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.162424 °	39.162424 °
				-121.934201 °	-121.934201 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23891
DS_ID:21368
EP_NO: 9969
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Landward slope too steep--need photo of the inside of concrete distribution box. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0158.
FIELD_STRUCT_DESC: 20-inch (not 24-inch as mentioned in the permit) steel irrigation discharge pipe through the levee, 27 feet below the crown. Corrugated metal cutoff wall around the pipe at the center of the levee. Pump and gate valve in a pump house on the waterside (WS) slope. Pipe discharges into a concrete box at the landside (LS) toe. (Retention of a 24-inch steel pipe through the levee, 27 feet below the crown, a pump and gate valve, a concrete box, and a service pole authorized under Automatic Board Order (ABO) No. 9969, 1974 - Edwin J. and Vivian L. Burrows). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 455+39), 24-inch listed].
FS Date: 10/22/2013

LM Start	2.61	Rating **	M	Issue No.	84 (cont)
LM End	2.61	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23891_41833.jpg



Pump station located on waterward side.

Photo 3 of 3 : UCIP_SP_2018_23891_41837.jpg



Dense vegetation covers pipe intake on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.78	Rating **	M	Issue No.	85	
LM End	2.78	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.160540 °	39.160540 °	
				-121.932382 °	-121.932382 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23892 DS_ID:21369 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0167. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 21 feet below the crown. Slide gate on the waterside (WS) end. (Cat. IVA). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013						

Photo 1 of 3 : UCIP_SP_2018_23892_41839.jpg



View of waterward side.

LM Start	2.78	Rating **	M	Issue No.	85 (cont)
LM End	2.78	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23892_41841.jpg



Buried screw gate located on waterward shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	2.78	Rating **	M	Issue No.	85 (cont)	
LM End	2.78	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.160540 °	39.160540 °	
				-121.932382 °	-121.932382 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23892 DS_ID:21369 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD1_2012_p_0167. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 21 feet below the crown. Slide gate on the waterside (WS) end. (Cat. IVA). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013						

Photo 3 of 3 : UCIP_SP_2018_23892_41840.jpg



Dense vegetation on the waterward edge.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.35	Rating **	M	Issue No.	86	
LM End	3.35	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.156068 °	39.156068 °	
				-121.923453 °	-121.923453 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24115 DS_ID:21370 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as USACE_CESPK_MRD2_2012_p_0197. FIELD_STRUCT_DESC: *ABANDONED* 24-inch drainage pipe of an unknown material through the levee, 18.5 feet below the crown. Slide gate on a concrete gate structure on the berm. [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013						

LM Start	3.35	Rating **	M	Issue No.	86 (cont)
LM End	3.35	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2018_24115_42495.jpg



View of waterward side--photo is from USACE PI Report draft final issue USACE_CESPK_MRD2_2012_p_0197.

Photo 2 of 2 : UCIP_SP_2018_24115_42496.jpg



View of landward side--photo is from USACE PI Report draft final issue USACE_CESPK_MRD2_2012_p_0197.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.40	Rating **	M	Issue No.	87
LM End	3.40	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.155648 °	39.155648 °
				-121.922823 °	-121.922823 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:24117					
DS_ID:21371					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as USACE_CESPK_MRD2_2012_p_0197.					
FIELD_STRUCT_DESC: *ABANDONED* 24-inch drainage pipe of an unknown material through the levee, 18.5 feet below the crown. Slide gate on a concrete gate structure on the berm. [Additional Reference(s): DWR Levee Log, 2007].					
FS Date: 10/22/2013					

LM Start	3.40	Rating **	M	Issue No.	87 (cont)
LM End	3.40	Issue Type +	En	Location *	

Photo 1 of 2 : UCIP_SP_2018_24117_42502.jpg



View of pipe on landward side.

Photo 2 of 2 : UCIP_SP_2018_24117_42501.jpg



View of concrete headwall and screw gate on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.46	Rating **	M	Issue No.	76
LM End	3.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.155008 °	39.155008 °
				-121.921905 °	-121.921905 °
DWR ID	DWR_RD0070_02_f_2017_76				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the waterside slope.					

Photo 1 of 1 : SP_2018_RD0070_30_76_20180305_00019.jpg



View of the rodent holes along the waterside slope.

LM Start	3.57	Rating **	M	Issue No.	50
LM End	3.57	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.154059 °	39.154059 °
				-121.920220 °	-121.920220 °
DWR ID	DWR_RD0070_02_f_2016_50				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

Photo 1 of 1 : SP_2018_RD0070_30_50_20180305_00004.jpg



View of the prunings along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.10	Rating **	M	Issue No.	88
LM End	4.10	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147298 °	39.147298 °
				-121.916724 °	-121.916724 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47028
 DS_ID:21428
 EP_NO: N/A
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Pump station will be removed. This crossing will need to be updated once the pump station is removed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
 FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 2] 1 of 4: 2.5-inch steel (not iron, as mentioned in the desk study) electrical conduit through the levee, 1.9 feet below the crown. Two concrete cutoff walls, one at each shoulder. Concrete pump pit on the waterside (WS) slope. Three pumps on a structure on the WS. Walkway to the pumps. Concrete headwall on the landside (LS). Debris deflectors in the river. (Plans for construction of a pumping plant and related facilities to replace an existing plant on the left bank of the Sacramento River authorized under Permit No. 4525, 1964 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
 FS Date: 10/22/2013

Photo 1 of 1 : UCIP_SP_2018_47028_42570.jpg



Conduits through levee along walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.10	Rating **	M	Issue No.	89
LM End	4.10	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147298 °	39.147298 °
				-121.916724 °	-121.916724 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47029
 DS_ID:21427
 EP_NO: N/A
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: Pump station to be removed. This record will need to be updated once the pump station is removed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
 FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 2] 2 of 4: 2.5-inch steel (not iron, as mentioned in the desk study) electrical conduit through the levee, 1.9 feet below the crown. Two concrete cutoff walls, one at each shoulder. Concrete pump pit on the waterside (WS) slope. Three pumps on a structure on the WS. Walkway to the pumps. Concrete headwall on the landside (LS). Debris deflectors in the river. (Plans for construction of a pumping plant and related facilities to replace an existing plant on the left bank of the Sacramento River authorized under Permit No. 4525, 1964 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
 FS Date: 10/22/2013

Photo 1 of 1 : UCIP_SP_2018_47029_42511.jpg



Conduits through levee along walkway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.11	Rating **	M	Issue No.	90
LM End	4.11	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147259 °	39.147259 °
				-121.916725 °	-121.916725 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47030
DS_ID:21429
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Pump is to be demolished will all pipes removed. Will need to update record. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 1] 3 of 4: 42-inch steel irrigation discharge pipe and 2-inch polyvinyl chloride (PVC) electrical conduit through the levee, 24 and 3 feet below the crown, respectively. 42-inch pipe is concrete encased through the levee. Two concrete cutoff walls, one at each shoulder. Slide gate in a surge box on the waterside (WS). Concrete pump pit on the WS slope. Three pumps on a structure on the WS. Walkway to the pumps with an electrical control box. Concrete headwall on the landside (LS). Pipe discharges into a concrete lined irrigation ditch on the LS. Debris deflectors in the river. Power poles on the LS. (Plans to enlarge the Meridian Farms Water Company Pump Station Facility No. 1 by adding a 150-horsepower pump, a 42-inch water pipe, and a 2-inch electrical conduit through the levee authorized under Permit No. 13380, 1982 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

Photo 1 of 3 : UCIP_SP_2018_47030_42563.jpg



View of walkway and pump station on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.11	Rating **	M	Issue No.	90 (cont)
LM End	4.11	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147259 °	39.147259 °
				-121.916725 °	-121.916725 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47030
DS_ID:21429
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Pump is to be demolished will all pipes removed. Will need to update record. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 1] 3 of 4: 42-inch steel irrigation discharge pipe and 2-inch polyvinyl chloride (PVC) electrical conduit through the levee, 24 and 3 feet below the crown, respectively. 42-inch pipe is concrete encased through the levee. Two concrete cutoff walls, one at each shoulder. Slide gate in a surge box on the waterside (WS). Concrete pump pit on the WS slope. Three pumps on a structure on the WS. Walkway to the pumps with an electrical control box. Concrete headwall on the landside (LS). Pipe discharges into a concrete lined irrigation ditch on the LS. Debris deflectors in the river. Power poles on the LS. (Plans to enlarge the Meridian Farms Water Company Pump Station Facility No. 1 by adding a 150-horsepower pump, a 42-inch water pipe, and a 2-inch electrical conduit through the levee authorized under Permit No. 13380, 1982 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

Photo 2 of 3 : UCIP_SP_2018_47030_42567.jpg



View of conduit pipes through levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.11	Rating **	M	Issue No.	90 (cont)
LM End	4.11	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147259 °	39.147259 °
				-121.916725 °	-121.916725 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47030
DS_ID:21429
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Pump is to be demolished will all pipes removed. Will need to update record. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 1] 3 of 4: 42-inch steel irrigation discharge pipe and 2-inch polyvinyl chloride (PVC) electrical conduit through the levee, 24 and 3 feet below the crown, respectively. 42-inch pipe is concrete encased through the levee. Two concrete cutoff walls, one at each shoulder. Slide gate in a surge box on the waterside (WS). Concrete pump pit on the WS slope. Three pumps on a structure on the WS. Walkway to the pumps with an electrical control box. Concrete headwall on the landside (LS). Pipe discharges into a concrete lined irrigation ditch on the LS. Debris deflectors in the river. Power poles on the LS. (Plans to enlarge the Meridian Farms Water Company Pump Station Facility No. 1 by adding a 150-horsepower pump, a 42-inch water pipe, and a 2-inch electrical conduit through the levee authorized under Permit No. 13380, 1982 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

Photo 3 of 3 : UCIP_SP_2018_47030_42569.jpg



View of pumps located on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.11	Rating **	M	Issue No.	91
LM End	4.11	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147247 °	39.147247 °
				-121.916691 °	-121.916691 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47032
DS_ID:21373
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Unable to confirm 54-inch pipe only found 42-inch pipe. Pump station is to be removed. Need to update record once crossing has been modified. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 2] 4 of 4: 54-inch steel irrigation discharge pipe through the levee, 24 feet below the crown. Pipe is concrete encased through the levee. Two concrete cutoff walls, one at each shoulder. Slide gate in a surge box on the waterside (WS). Concrete pump pit on the WS slope. Three pumps on a structure on the WS. Walkway to the pumps. Concrete headwall on the landside (LS). Pipe discharges into a concrete lined irrigation ditch on the LS. Debris deflectors in the river. (Plans for construction of a pumping plant and related facilities to replace an existing plant on the left bank of the Sacramento River authorized under Permit No. 4525, 1964 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

LM Start	4.11	Rating **	M	Issue No.	91 (cont)
LM End	4.11	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_47032_42076.jpg



View of walkway and pump station on waterward side.

Photo 2 of 3 : UCIP_SP_2018_47032_42080.jpg



View of conduit pipes through levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.11	Rating **	M	Issue No.	91 (cont)
LM End	4.11	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.147247 °	39.147247 °	
			-121.916691 °	-121.916691 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:47032
DS_ID:21373
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Unable to confirm 54-inch pipe only found 42-inch pipe. Pump station is to be removed. Need to update record once crossing has been modified. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0235.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 2] 4 of 4: 54-inch steel irrigation discharge pipe through the levee, 24 feet below the crown. Pipe is concrete encased through the levee. Two concrete cutoff walls, one at each shoulder. Slide gate in a surge box on the waterside (WS). Concrete pump pit on the WS slope. Three pumps on a structure on the WS. Walkway to the pumps. Concrete headwall on the landside (LS). Pipe discharges into a concrete lined irrigation ditch on the LS. Debris deflectors in the river. (Plans for construction of a pumping plant and related facilities to replace an existing plant on the left bank of the Sacramento River authorized under Permit No. 4525, 1964 - Meridian Farms Water Company. Plans for existing pumping plant to be demolished with all pipes removed and replaced with a new Meridian Diversion pumping facility, two retractable fish screens, and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/22/2013

Photo 3 of 3 : UCIP_SP_2018_47032_42082.jpg



View of pumps located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.12	Rating **	M	Issue No.	92
LM End	4.12	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.147072 °	39.147072 °
				-121.916783 °	-121.916783 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:24165 DS_ID:21374 EP_NO: 767 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine if crossing is still active and to determine last inspection date. Will need copy of letter showing crossings passed inspection. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0237. FIELD_STRUCT_DESC: 3-inch steel natural gas pipeline (not 3.5-inch, as mentioned in the desk study) through the levee, 3 feet below the crown. 8-foot by 10-foot by 1-foot concrete inspection well with a metal cover on the waterside (WS) shoulder. Rock revetment on the WS slope. Painted aluminum marker on the WS. Contact information provided on marker: (916) 742-7344 and for emergencies call (916) 742-3251. (Plans for the construction of a natural gas pipeline across the Sacramento River and the east and west levees thereof authorized under Permit No. 767, 1938 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/22/2013					

LM Start	4.12	Rating **	M	Issue No.	92 (cont)
LM End	4.12	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24165_42573.jpg



View of levee crown.

Photo 2 of 3 : UCIP_SP_2018_24165_42575.jpg



Concrete headwall on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.17	Rating **	M	Issue No.	93
LM End	4.17	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.146374 °	39.146374 °
				-121.916980 °	-121.916980 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23959 DS_ID:21375 EP_NO: 1123 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No connection present. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0240. FIELD_STRUCT_DESC: 1 of 3: 10-inch water supply pipe of an unknown material through the levee, 2 feet below the crown. Seed washing plant with concrete catch basin and pan on the landside (LS) slope. Concrete sump on the waterside (WS) slope. Intake pump on the WS slope. (Plans for installing a seed washer on the LS slope and influent and effluent pipes through the levee authorized under Permit No. 1123, 1946 - G. J. Reitter). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 496+25)]. FS Date: 10/22/2013					

Photo 1 of 1 : UCIP_SP_2018_23959_42096.jpg



Concrete headwall located on landward side--no pipe. Only visible pipe is the pipe located at the far left (downstream end).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.17	Rating **	M	Issue No.	94	
LM End	4.17	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.146331 °	39.146331 °	
				-121.916985 °	-121.916985 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23960 DS_ID:21424 EP_NO: 1123 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No connection present. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0240. FIELD_STRUCT_DESC: 2 of 3: 4-inch water supply pipe of an unknown material through the levee, 2 feet below the crown. Seed washing plant with concrete catch basin and pan on the landside (LS) slope. Concrete sump on the waterside (WS) slope. Intake pump on the WS slope. (Plans for installing a seed washer on the LS slope and influent and effluent pipes through the levee authorized under Permit No. 1123, 1946 - G. J. Reitter). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 496+25)]. FS Date: 10/22/2013						

Photo 1 of 1 : UCIP_SP_2018_23960_42097.jpg



Concrete headwall located on landward side--no pipe. Only visible pipe is the pipe located at the far left (downstream end).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.17	Rating **	M	Issue No.	95	
LM End	4.17	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.146298 °	39.146298 °	
				-121.916993 °	-121.916993 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23961						
DS_ID:21425						
EP_NO: 1123						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: No connection present. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item						
USACE_CESPK_MRD2_2012_p_0240.						
FIELD_STRUCT_DESC: 3 of 3: 8-inch water supply pipe of an unknown material through the levee, 2 feet below the crown. Seed washing plant with concrete catch basin and pan on the landside (LS) slope. Concrete sump on the waterside (WS) slope. Intake pump on the WS slope.						
[Additional Reference(s): USACE Sacramento O&M Manual 134, June 1953, (Station 496+25)].						
FS Date: 10/22/2013						

Photo 1 of 1 : UCIP_SP_2018_23961_42098.jpg



Concrete headwall located on landward side--no pipe. Only visible pipe is the pipe located at the far left (downstream end).

LM Start	4.31	Rating **	M	Issue No.	51
LM End	4.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.144305 °	39.144305 °
				-121.917400 °	-121.917400 °
DWR ID	DWR_RD0070_02_f_2016_51				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.38	Rating **	M	Issue No.	52
LM End	4.38	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.143424 °	39.143424 °
				-121.917704 °	-121.917704 °
DWR ID	DWR_RD0070_02_f_2016_52				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.55	Rating **	M	Issue No.	96
LM End	4.55	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.141254 °	39.141254 °
				-121.919221 °	-121.919221 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23962
DS_ID:21379
EP_NO: 9998
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Unable to confirm if crossing corresponds to permit 9998. Pipe size is different then the pipe size listed in the desk study. Unable to confirm if structure on landward side is a pump house. Need to coordinate with owner to obtain permit record for crossing. Need to verify status of crossing. Permit authorized 24 inch pipe. Pipe through levee is 30 inches. Unable to find stand pipe in field. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0264.
FIELD_STRUCT_DESC: 30-inch (not 24-inch as indicated in desk study) corrugated metal irrigation discharge pipe through the levee, 15.5 feet below the crown. Slide gate in a concrete distribution box at the landside (LS) toe. Pump in a pump house on the LS. Service pole and ramp on the waterside (WS) slope. Concrete box with air vents on the WS end. (Retention of a 24-inch corrugated metal pipe (CMP) through the levee, 15.5 feet below the crown, a pump, a slide gate, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9998, 1974 - Robert Tod Ruse, Trustee. Plans to install an 18-inch polyvinyl chloride (PVC) pipe through an existing 24-inch steel pipe under the levee with annular space grouted authorized under Permit No. 16228, 1994 - Mike and Carol Churkin). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 516+06)].
FS Date: 10/22/2013

Photo 1 of 3 : UCIP_SP_2018_23962_42099.jpg



View of pump house located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.55	Rating **	M	Issue No.	96 (cont)	
LM End	4.55	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.141254 °	39.141254 °	
				-121.919221 °	-121.919221 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23962 DS_ID:21379 EP_NO: 9998 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Unable to confirm if crossing corresponds to permit 9998. Pipe size is different then the pipe size listed in the desk study. Unable to confirm if structure on landward side is a pump house. Need to coordinate with owner to obtain permit record for crossing. Need to verify status of crossing. Permit authorized 24 inch pipe. Pipe through levee is 30 inches. Unable to find stand pipe in field. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0264. FIELD_STRUCT_DESC: 30-inch (not 24-inch as indicated in desk study) corrugated metal irrigation discharge pipe through the levee, 15.5 feet below the crown. Slide gate in a concrete distribution box at the landside (LS) toe. Pump in a pump house on the LS. Service pole and ramp on the waterside (WS) slope. Concrete box with air vents on the WS end. (Retention of a 24-inch corrugated metal pipe (CMP) through the levee, 15.5 feet below the crown, a pump, a slide gate, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9998, 1974 - Robert Tod Ruse, Trustee. Plans to install an 18-inch polyvinyl chloride (PVC) pipe through an existing 24-inch steel pipe under the levee with annular space grouted authorized under Permit No. 16228, 1994 - Mike and Carol Churkin). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 516+06)]. FS Date: 10/22/2013						

Photo 2 of 3 : UCIP_SP_2018_23962_42104.jpg



Positive closure device located at the waterward side inside concrete distribution box.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.55	Rating **	M	Issue No.	96 (cont)
LM End	4.55	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.141254 °	39.141254 °
				-121.919221 °	-121.919221 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23962
DS_ID:21379
EP_NO: 9998
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Unable to confirm if crossing corresponds to permit 9998. Pipe size is different then the pipe size listed in the desk study. Unable to confirm if structure on landward side is a pump house. Need to coordinate with owner to obtain permit record for crossing. Need to verify status of crossing. Permit authorized 24 inch pipe. Pipe through levee is 30 inches. Unable to find stand pipe in field. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0264.
FIELD_STRUCT_DESC: 30-inch (not 24-inch as indicated in desk study) corrugated metal irrigation discharge pipe through the levee, 15.5 feet below the crown. Slide gate in a concrete distribution box at the landside (LS) toe. Pump in a pump house on the LS. Service pole and ramp on the waterside (WS) slope. Concrete box with air vents on the WS end. (Retention of a 24-inch corrugated metal pipe (CMP) through the levee, 15.5 feet below the crown, a pump, a slide gate, a service pole, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9998, 1974 - Robert Tod Ruse, Trustee. Plans to install an 18-inch polyvinyl chloride (PVC) pipe through an existing 24-inch steel pipe under the levee with annular space grouted authorized under Permit No. 16228, 1994 - Mike and Carol Churkin). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 516+06)].
FS Date: 10/22/2013

Photo 3 of 3 : UCIP_SP_2018_23962_42101.jpg



Photo of the concrete distribution box located on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.59	Rating **	M	Issue No.	53
LM End	4.59	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.140975 °	39.140975 °
				-121.919907 °	-121.919907 °
DWR ID	DWR_RD0070_02_f _ 2016_53				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					


Photo 1 of 1 : SP_2018_RD0070_30_53_20180305_00005.jpg



View of the prunings along the landside toe.

LM Start	4.76	Rating **	M	Issue No.	97	
LM End	4.76	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.141136 °	39.141136 °	
				-121.922785 °	-121.922785 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24166 DS_ID:21380 EP_NO: 9970 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to coordinate with owner to determine status of crossing. No pump is located inside the pump house located on waterward side. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0274. FIELD_STRUCT_DESC: 10-inch steel irrigation discharge pipe through the levee, 4.8 feet below the crown. Corrugated metal cutoff wall around the pipe at the center of the levee. Siphon breaker on the landside (LS) slope, not found. Pump in a pump house on the waterside (WS) shoulder. Shutoff valve on the LS. Concrete discharge box at the LS toe. (Retention of a 10-inch steel pipe through the levee, 4.8 feet below the crown, a pump, a service pole, a siphon breaker, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9970, 1974 - Arnold Chesini). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 526+71)]. FS Date: 10/22/2013						

Photo 1 of 3 : UCIP_SP_2018_24166_42581.jpg



Enter photo 7 description or comment here.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.76	Rating **	M	Issue No.	97 (cont)
LM End	4.76	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.141136 °	39.141136 °
				-121.922785 °	-121.922785 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24166

DS_ID:21380

EP_NO: 9970

Repair Type: Non-Urgent

Crossing Status: Found

UCIP Comments: Need to coordinate with owner to determine status of crossing. No pump is located inside the pump house located on waterward side. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0274.

FIELD_STRUCT_DESC: 10-inch steel irrigation discharge pipe through the levee, 4.8 feet below the crown. Corrugated metal cutoff wall around the pipe at the center of the levee. Siphon breaker on the landside (LS) slope, not found. Pump in a pump house on the waterside (WS) shoulder. Shutoff valve on the LS. Concrete discharge box at the LS toe. (Retention of a 10-inch steel pipe through the levee, 4.8 feet below the crown, a pump, a service pole, a siphon breaker, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9970, 1974 - Arnold Chesini). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 526+71)].

FS Date: 10/22/2013

LM Start	4.76	Rating **	M	Issue No.	97 (cont)
LM End	4.76	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_24166_42580.jpg



View of levee crown and pump house photo taken from landward side.

Photo 3 of 3 : UCIP_SP_2018_24166_42583.jpg



View of the inside of pump house--no pump.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	4.95	Rating **	M	Issue No.	54
LM End	4.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.142016 °	39.142016 °
				-121.926214 °	-121.926214 °
DWR ID	DWR_RD0070_02_f_2016_54				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_54_20180305_00006.jpg



View of the trees blocking visibility.

LM Start	4.95	Rating **	U	Issue No.	9
LM End	4.98	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.142008 °	39.142032 °
				-121.926267 °	-121.926855 °
DWR ID	DWR_RD0070_02_s_2012_9				
Comment Code					
BU : Building					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_9_20180305_00003.jpg



View of a building within the easement of the levee.

LM Start	5.08	Rating **	M	Issue No.	47
LM End	5.08	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.141938 °	39.141938 °
				-121.928597 °	-121.928597 °
DWR ID	DWR_RD0070_02_s_2018_47				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside toe.					

Photo 1 of 1 : SP_2018_RD0070_30_47_20180402_00125.jpg



View of the prunings along the landside toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	5.30	Rating **	M	Issue No.	98	
LM End	5.30	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.142049 °	39.142049 °	
				-121.932651 °	-121.932651 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23964 DS_ID:21383 EP_NO: 9984 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Will need to contact owner. Need to obtain maintenance records and clarify modifications made at to crossing (size). Additional crossing visible through concrete headwall on landward side--crossing has been capped (see photo). NEED TO CONFIRM PIPE SIZE!!! This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0289. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe (not 24-inch, as referenced in the permit) through the levee, 13.8 feet below the crown. Gate valve on the waterside (WS). Pump in a pump house on the WS. Concrete distribution box at the landside (LS) toe. (Retention of a 24-inch steel pipe through the levee, 13.8 feet below the crown, a pump, a gate valve, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9984, 1974 - Edward E. and Alice B. Lemos, et al.). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 555+09), 24-inch listed]. FS Date: 10/22/2013						

Photo 1 of 3 : UCIP_SP_2018_23964_42114.jpg



Pump house located on waterward side.

LM Start	5.30	Rating **	M	Issue No.	98 (cont)
LM End	5.30	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23964_42116.jpg



No pipe exists the pump house on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	5.30	Rating **	M	Issue No.	98 (cont)							
LM End	5.30	Issue Type +	En	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP Field Study		39.142049 °	39.142049 °								
			-121.932651 °	-121.932651 °								
DWR ID												
Comment Code												
Inspector Comment												
FS_ID:23964 DS_ID:21383 EP_NO: 9984 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Will need to contact owner. Need to obtain maintenance records and clarify modifications made at to crossing (size). Additional crossing visible through concrete headwall on landward side--crossing has been capped (see photo). NEED TO CONFIRM PIPE SIZE!!! This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0289. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe (not 24-inch, as referenced in the permit) through the levee, 13.8 feet below the crown. Gate valve on the waterside (WS). Pump in a pump house on the WS. Concrete distribution box at the landside (LS) toe. (Retention of a 24-inch steel pipe through the levee, 13.8 feet below the crown, a pump, a gate valve, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9984, 1974 - Edward E. and Alice B. Lemos, et al.). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 555+09), 24-inch listed]. FS Date: 10/22/2013												

Photo 3 of 3 : UCIP_SP_2018_23964_42113.jpg



Crossing appears altered on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.28	Rating **	M	Issue No.	99
LM End	6.28	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.133847 °	39.133847 °
				-121.937689 °	-121.937689 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23965
DS_ID:21385
EP_NO: 4383
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to contact owner to determine if crossing is still active and to determine last inspection date. Will need copy of letter showing crossings passed inspection. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0319.
FIELD_STRUCT_DESC: 8.625-inch steel natural gas pipeline through the levee, 3.5 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Rock revetment on the waterside (WS) slope. (Plans for construction, maintenance, and use of an 8.625-inch gas line authorized under Permit No. 4383, 1963 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/23/2013

LM Start	6.28	Rating **	M	Issue No.	99 (cont)
LM End	6.28	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23965_42123.jpg



Markers visible on both levee shoulders.

Photo 2 of 3 : UCIP_SP_2018_23965_42121.jpg



View of waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.28	Rating **	M	Issue No.	99 (cont)	
LM End	6.28	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.133847 °	39.133847 °	
				-121.937689 °	-121.937689 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23965 DS_ID:21385 EP_NO: 4383 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine if crossing is still active and to determine last inspection date. Will need copy of letter showing crossings passed inspection. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0319. FIELD_STRUCT_DESC: 8.625-inch steel natural gas pipeline through the levee, 3.5 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Rock revetment on the waterside (WS) slope. (Plans for construction, maintenance, and use of an 8.625-inch gas line authorized under Permit No. 4383, 1963 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_23965_42122.jpg



Sign visible on waterward side.

LM Start	6.32	Rating **	M	Issue No.	56
LM End	7.09	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.133450 °	39.129024 °
				-121.937361 °	-121.924632 °
DWR ID	DWR_RD0070_02_f_2016_56				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_56_20180305_00007.jpg



View of a ditch at the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.33	Rating **	M	Issue No.	100
LM End	6.33	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.133219 °	39.133219 °
				-121.937169 °	-121.937169 °
DWR ID					

Comment Code

--

Inspector Comment

FS_ID:46424
DS_ID:21386
EP_NO: 9994
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 07/28/2015 System was running during site visit. Damage to landward side has been repaired. No records available to determine cause of erosion--monitor. No other issues observed during site visit. 10/23/2013 Erosion visible on landward side behind concrete headwall. Plastic sheeting has been placed to protect slope. Need to determine cause for erosion, is pipe leaking? Pipe wall on landward side has deteriorated significantly that the wall is gone. Owner will need to coordinate with DWR inspector and CVFPB to address issue. Recommend notifying owner to stop using crossing until issue has been addressed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0324.
FIELD_STRUCT_DESC: 20-inch coated steel irrigation discharge pipe on the waterside (WS) and 24-inch coated steel irrigation discharge pipe on the landside (LS) through the levee, 12.5 feet below the crown. Pipe is concrete encased under the crown, between the shoulders. Slide gate in a metal well on the WS slope. Pump on a pile structure in the stream. Concrete discharge box at the LS toe. Service pole on the WS slope. (Plans for the installation of an irrigation pumping plant and appurtenant electrical power line across the levee authorized under Permit No. 1202, 19 - Hannah R. Jacobs. Retention of a 24-inch concrete encased steel pipe through the levee, 12.5 feet below the crown, a pump, a slide gate, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9994, 1974 - R. X. Ranch Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 610+84)].
FS Date: 7/28/2015 3:46:00 PM

Photo 1 of 3 : UCIP_SP_2018_46424_42043.jpg



View of levee slope and berm on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.33	Rating **	M	Issue No.	100 (cont)
LM End	6.33	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.133219 °	39.133219 °
				-121.937169 °	-121.937169 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:46424
 DS_ID:21386
 EP_NO: 9994
 Repair Type: Non-Urgent
 Crossing Status: Found
 UCIP Comments: 07/28/2015 System was running during site visit. Damage to landward side has been repaired. No records available to determine cause of erosion--monitor. No other issues observed during site visit. 10/23/2013 Erosion visible on landward side behind concrete headwall. Plastic sheeting has been placed to protect slope. Need to determine cause for erosion, is pipe leaking? Pipe wall on landward side has deteriorated significantly that the wall is gone. Owner will need to coordinate with DWR inspector and CVFPB to address issue. Recommend notifying owner to stop using crossing until issue has been addressed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0324.
 FIELD_STRUCT_DESC: 20-inch coated steel irrigation discharge pipe on the waterside (WS) and 24-inch coated steel irrigation discharge pipe on the landside (LS) through the levee, 12.5 feet below the crown. Pipe is concrete encased under the crown, between the shoulders. Slide gate in a metal well on the WS slope. Pump on a pile structure in the stream. Concrete discharge box at the LS toe. Service pole on the WS slope. (Plans for the installation of an irrigation pumping plant and appurtenant electrical power line across the levee authorized under Permit No. 1202, 19 - Hannah R. Jacobs. Retention of a 24-inch concrete encased steel pipe through the levee, 12.5 feet below the crown, a pump, a slide gate, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9994, 1974 - R. X. Ranch Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 610+84)].
 FS Date: 7/28/2015 3:46:00 PM

Photo 2 of 3 : UCIP_SP_2018_46424_42049.jpg



Pipe and pump set up on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.33	Rating **	M	Issue No.	100 (cont)	
LM End	6.33	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.133219 °	39.133219 °	
				-121.937169 °	-121.937169 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46424 DS_ID:21386 EP_NO: 9994 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 07/28/2015 System was running during site visit. Damage to landward side has been repaired. No records available to determine cause of erosion--monitor. No other issues observed during site visit. 10/23/2013 Erosion visible on landward side behind concrete headwall. Plastic sheeting has been placed to protect slope. Need to determine cause for erosion, is pipe leaking? Pipe wall on landward side has deteriorated significantly that the wall is gone. Owner will need to coordinate with DWR inspector and CVFPB to address issue. Recommend notifying owner to stop using crossing until issue has been addressed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0324. FIELD_STRUCT_DESC: 20-inch coated steel irrigation discharge pipe on the waterside (WS) and 24-inch coated steel irrigation discharge pipe on the landside (LS) through the levee, 12.5 feet below the crown. Pipe is concrete encased under the crown, between the shoulders. Slide gate in a metal well on the WS slope. Pump on a pile structure in the stream. Concrete discharge box at the LS toe. Service pole on the WS slope. (Plans for the installation of an irrigation pumping plant and appurtenant electrical power line across the levee authorized under Permit No. 1202, 19 - Hannah R. Jacobs. Retention of a 24-inch concrete encased steel pipe through the levee, 12.5 feet below the crown, a pump, a slide gate, and a concrete discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9994, 1974 - R. X. Ranch Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 610+84)]. FS Date: 7/28/2015 3:46:00 PM						

Photo 3 of 3 : UCIP_SP_2018_46424_42047.jpg



Stairs and platform located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.99	Rating **	C	Issue No.	67
LM End	6.99	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.129557 °	39.129557 °
				-121.926343 °	-121.926343 °
DWR ID	DWR_RD0070_02_s_2017_67				
Comment Code					
TR : Tree or limb					
Inspector Comment					
The tree was removed from the waterside toe.					

No Photos

LM Start	7.18	Rating **	M	Issue No.	57
LM End	7.18	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.128114 °	39.128114 °
				-121.923429 °	-121.923429 °
DWR ID	DWR_RD0070_02_f_2016_57				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_57_20180305_00008.jpg



View of a ditch along the landside toe.

LM Start	7.62	Rating **	U	Issue No.	58
LM End	7.64	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.124448 °	39.124493 °
				-121.917505 °	-121.917090 °
DWR ID	DWR_RD0070_02_f_2016_58				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

Photo 1 of 1 : SP_2018_RD0070_30_58_20180305_00009.jpg



View of the prunings along the landside toe.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.74	Rating **	N	Issue No.	59
LM End	7.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.124503 °	39.124503 °
				-121.915252 °	-121.915252 °
DWR ID	DWR_RD0070_02_f_2016_59				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	7.82	Rating **	M	Issue No.	101	
LM End	7.82	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.124562 °	39.124562 °	
				-121.913758 °	-121.913758 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23966 DS_ID:21387 EP_NO: 9966 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Pipe daylight at waterward side blocked. Unable to determine if connection is present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0371. FIELD_STRUCT_DESC: 10-inch coated steel irrigation discharge pipe and 1.5-inch electrical conduit of an unknown material through the levee, 12 feet and 8 feet below the crown, respectively. Pipe is concrete encased under the crown, between the shoulders. Concrete cutoff wall under each shoulder. Pump and gate valve on a pile structure in the stream. Walkway to the pump. Concrete standpipe on the landside (LS). (Retention of a 24-inch corrugated metal drainage pipe through the levee, 13 feet below the crown, a flap gate, and two concrete headwalls authorized under Automatic Board Order (ABO) issued as Permit No. 11496, 1976 - Earl Foutch). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 689+50)]. FS Date: 10/23/2013						

Photo 1 of 3 : UCIP_SP_2018_23966_42128.jpg



Pump house located on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.82	Rating **	M	Issue No.	101 (cont)
LM End	7.82	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.124562 °	39.124562 °
				-121.913758 °	-121.913758 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:23966
DS_ID:21387
EP_NO: 9966
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Pipe daylight at waterward side blocked. Unable to determine if connection is present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Unable to determine if crossing is in use. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0371.
FIELD_STRUCT_DESC: 10-inch coated steel irrigation discharge pipe and 1.5-inch electrical conduit of an unknown material through the levee, 12 feet and 8 feet below the crown, respectively. Pipe is concrete encased under the crown, between the shoulders. Concrete cutoff wall under each shoulder. Pump and gate valve on a pile structure in the stream. Walkway to the pump. Concrete standpipe on the landside (LS). (Retention of a 24-inch corrugated metal drainage pipe through the levee, 13 feet below the crown, a flap gate, and two concrete headwalls authorized under Automatic Board Order (ABO) issued as Permit No. 11496, 1976 - Earl Foutch). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 689+50)].
FS Date: 10/23/2013

LM Start	7.82	Rating **	M	Issue No.	101 (cont)
LM End	7.82	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23966_42126.jpg



Concrete headwall located on waterward side.

Photo 3 of 3 : UCIP_SP_2018_23966_42127.jpg



Stand pipe located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.92	Rating **	M	Issue No.	102
LM End	7.92	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.124543 °	39.124543 °
				-121.911996 °	-121.911996 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:24191 DS_ID:21389 EP_NO: 1264 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0124. FIELD_STRUCT_DESC: *ABANDONED* 10-inch (not 14-inch as specified in the permit) irrigation discharge pipe of an unknown material through the levee, 5 feet below the crown. Pump on the waterside (WS). Double concrete discharge box at the landside (LS) toe. (Plans for installing an irrigation pumping plant and a 14-inch steel discharge pipe through the levee authorized under Permit No. 1264, 1948 - Robert Chesney). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013					

Photo 1 of 3 : UCIP_SP_2018_24191_42677.jpg



View of levee crown at crossing.

LM Start	7.92	Rating **	M	Issue No.	102 (cont)
LM End	7.92	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_24191_42678.jpg



View of waterward side--only pump house of nearby crossing located downstream from crossing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.92	Rating **	M	Issue No.	102 (cont)	
LM End	7.92	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.124543 °	39.124543 °	
				-121.911996 °	-121.911996 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24191 DS_ID:21389 EP_NO: 1264 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0124. FIELD_STRUCT_DESC: *ABANDONED* 10-inch (not 14-inch as specified in the permit) irrigation discharge pipe of an unknown material through the levee, 5 feet below the crown. Pump on the waterside (WS). Double concrete discharge box at the landside (LS) toe. (Plans for installing an irrigation pumping plant and a 14-inch steel discharge pipe through the levee authorized under Permit No. 1264, 1948 - Robert Chesney). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24191_42676.jpg



View of landward side--two crossing nearby.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.92	Rating **	M	Issue No.	103
LM End	7.92	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.124460 °	39.124460 °	
			-121.911932 °	-121.911932 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:24190
DS_ID:21388
EP_NO: 10008
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Concrete distribution box is damage on waterward side. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0380.
FIELD_STRUCT_DESC: *ABANDONED* 18-inch steel irrigation discharge pipe through the levee, 15 feet below the crown. Pump in a pump house on the waterside (WS). Slide gate on the WS. Concrete distribution box on the landside (LS). During field verification, additional appurtenances were observed. An additional pipe on the LS drains into the concrete distribution box. The concrete distribution box connects to a second set of distribution boxes through a 24-inch reinforced concrete pipe approximately 36 feet upstream of the crossing. Those boxes have a 10-inch pipe which appears to go through the levee. (Retention of an 18-inch corrugated metal pipe (CMP) through the levee, 15 feet below the crown, a pump, a slide gate, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 10008, 1974 - Frances C. Yates). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 694+85)].
FS Date: 10/23/2013

LM Start	7.92	Rating **	M	Issue No.	103 (cont)
LM End	7.92	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24190_42667.jpg



View of levee crown at crossing.

Photo 2 of 3 : UCIP_SP_2018_24190_42668.jpg



Pump house located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.92	Rating **	M	Issue No.	103 (cont)
LM End	7.92	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.124460 °	39.124460 °
				-121.911932 °	-121.911932 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24190
DS_ID:21388
EP_NO: 10008
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Concrete distribution box is damage on waterward side. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0380.
FIELD_STRUCT_DESC: *ABANDONED* 18-inch steel irrigation discharge pipe through the levee, 15 feet below the crown. Pump in a pump house on the waterside (WS). Slide gate on the WS. Concrete distribution box on the landside (LS). During field verification, additional appurtenances were observed. An additional pipe on the LS drains into the concrete distribution box. The concrete distribution box connects to a second set of distribution boxes through a 24-inch reinforced concrete pipe approximately 36 feet upstream of the crossing. Those boxes have a 10-inch pipe which appears to go through the levee. (Retention of an 18-inch corrugated metal pipe (CMP) through the levee, 15 feet below the crown, a pump, a slide gate, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 10008, 1974 - Frances C. Yates). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 694+85)].
FS Date: 10/23/2013

Photo 3 of 3 : UCIP_SP_2018_24190_42669.jpg



Damage concrete distribution box located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.96	Rating **	C	Issue No.	78
LM End	7.96	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.124227 °	39.124227 °
				-121.911290 °	-121.911290 °
DWR ID	DWR_RD0070_02_f_2017_78				
Comment Code					
PR : Prunings					
Inspector Comment					
The prunings was removed from the waterside toe.					

No Photos

LM Start	8.10	Rating **	M	Issue No.	2
LM End	8.23	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.122459 °	39.120684 °
				-121.910121 °	-121.909152 °
DWR ID	DWR_RD0070_02_s_2016_2				
Comment Code					
Inspector Comment					
1997 - Critical Site - Erosion of cobble site on outside of a bend. Failure caused by erosion of a material from behind the cobbles and cobbles rolling down the slope. Failure is just above the toe levee. Some repairs had been done at the upstream end. 2004 - Some minor new erosion at the top of the berm. 2005 - Trees look okay and the downstream end has some new rock repair. Site is no longer critical. 2006 - No longer critical, some repairs. 2015: No observed changes. [2015 Site ID: SAC_130-0_L]					

Photo 1 of 1 : SP_2018_RD0070_30_2_20180305_00002.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	8.10	Rating **	M	Issue No.	60
LM End	8.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.122568 °	39.122568 °
				-121.909723 °	-121.909723 °
DWR ID	DWR_RD0070_02_f_2016_60				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	8.12	Rating **	M	Issue No.	104
LM End	8.12	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.122347 °	39.122347 °
				-121.909592 °	-121.909592 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50007
DS_ID:21390
EP_NO: 10371
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 7/07/2016 Crossing was downgraded from Urgent to Non-Urgent -- siphon breaker leak was repaired back in September 2015. Still need to coordinate with owner for additional details regarding pipe (install date, owner confirmation, and crossing size change from 15-inch to 12-inch). Also dense vegetation visible along pipe on both WS and LS slopes. (DWR UCIP - omagana)9/15/2015 Leak was caused by leaky siphon breaker. Siphon breaker was repaired and a protective encasing around the siphon breaker was installed. Levee was repaired. Need to contact owner to determine additional information regarding the pipe. (DWR UCIP - omagana)7/28/2015 Hole present on waterward slope has gotten worse since last inspection. The hole is located less than 2 feet from S Meridian Road (county road). Dense vegetation on waterward slope limits visual inspection to determine extent of levee damage or cause. According to LMA representative the damage on the slope was caused by leaky siphon breaker. LMA representative has notified owner to stop use of pipe. Based on the extent of the damage visible from prior inspection and the age of the pipe, this pipe would be a good candidate for video or pressure test to confirm the integrity of pipe through levee (county road). Owner will need to coordinate with DWR Inspector and CVFPB to address leaky pipe per Title 23 requirements. (DWR UCIP - omagana)10/23/2013 Pipe leaking on waterward side. Recommend LMA superintendent notify owner to stop using crossing to avoid further damage to levee slope. Owner will need to coordinate with DWR Inspector and CVFPB to address leaky pipe per Title 23 requirements. Also recommend having owner clear out some of the vegetation along the pipe alignment (below pump station) to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0391. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 12-inch coated steel irrigation discharge pipe and electrical conduit of an unknown material through the levee, 3 and 2 feet below the crown, respectively. Steel cutoff wall around the pipe and conduit at the center of the levee. Siphon breaker in a protective housing on the waterside (WS) shoulder. Discharge structure at the landside (LS) toe. Slant pump on the WS. Power pole on the LS. (Plans to install a slant pump with a 12-inch irrigation pipe through the levee authorized under Permit No. 10371, 1974 - Frances Yates, care of Gillett-Harris-Duranceau/Associates. Plans to install a slant pump and motor in the channel and a discharge pipe through the levee authorized under Permit 10371-A, 1979 - Roy Moresco. Unknown permit authorizing current 12-inch pipe). [Additional Reference(s): DWR Levee

Photo 1 of 3 : UCIP_SP_2018_50007_42684.jpg



Vegetation on WS where leak found.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

Log, 2007].

FS Date: 7/7/2016 10:38:00 AM

LM Start	8.12	Rating **	M	Issue No.	104 (cont)
LM End	8.12	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_50007_42680.jpg



Damage to WS shoulder due to leaky pipe or siphon breaker.

LM Start	8.12	Rating **	M	Issue No.	104 (cont)
LM End	8.12	Issue Type +	En	Location *	

Photo 3 of 3 : UCIP_SP_2018_50007_74614.jpg



Slope damage within 2 feet of County Road.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	9.00	Rating **	M	Issue No.	105
LM End	9.00	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.110878 °	39.110878 °
				-121.902775 °	-121.902775 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24108
DS_ID:21423
EP_NO: 9971
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Will need to contact owner. Need to obtain maintenance records and clarify modifications made to crossing (size). This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0433.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 3] 2 of 3: 16-inch irrigation discharge pipe of an unknown material (not a 30-inch pipe, as mentioned in the desk study) through the levee, 20.5 feet below the crown. Gate valve on the waterside (WS) end. Pump on a pile structure in the stream. Wooden walkway to the pump. Concrete distribution box on the landside (LS). (Retention of a 30-inch steel pipe through the levee, 20.5 feet below the crown, a pump, a gate valve, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9971, 1974 - Georgia Chesney, Life Estate. Plans to demolish and remove the existing Meridian Diversion Pumping Facility and the existing Drexler Diversion Pumping Facility and to construct a new Meridian Diversion Pumping Facility with two retractable fish screens and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/23/2013

LM Start	9.00	Rating **	M	Issue No.	105 (cont)
LM End	9.00	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24108_42463.jpg



View of landward side--pump station and walkway

Photo 2 of 3 : UCIP_SP_2018_24108_42465.jpg



View of 16-inch pipe and 24-inch pipe with screw gate located on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	9.00	Rating **	M	Issue No.	105 (cont)
LM End	9.00	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.110878 °	39.110878 °
				-121.902775 °	-121.902775 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24108
DS_ID:21423
EP_NO: 9971
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Will need to contact owner. Need to obtain maintenance records and clarify modifications made to crossing (size). This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0433.
FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 3] 2 of 3: 16-inch irrigation discharge pipe of an unknown material (not a 30-inch pipe, as mentioned in the desk study) through the levee, 20.5 feet below the crown. Gate valve on the waterside (WS) end. Pump on a pile structure in the stream. Wooden walkway to the pump. Concrete distribution box on the landside (LS). (Retention of a 30-inch steel pipe through the levee, 20.5 feet below the crown, a pump, a gate valve, and a concrete distribution box authorized under Automatic Board Order (ABO) issued as Permit No. 9971, 1974 - Georgia Chesney, Life Estate. Plans to demolish and remove the existing Meridian Diversion Pumping Facility and the existing Drexler Diversion Pumping Facility and to construct a new Meridian Diversion Pumping Facility with two retractable fish screens and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/23/2013

Photo 3 of 3 : UCIP_SP_2018_24108_42464.jpg



View of 16-inch pipe and 24-inch pipe located on waterward side.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	9.01	Rating **	M	Issue No.	106	
LM End	9.01	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.110869 °	39.110869 °	
				-121.902771 °	-121.902771 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24107 DS_ID:21394 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pump station is to be demolished. This crossing will need to be updated once the work has been completed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0433. FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 3] 3 of 3: 24-inch irrigation discharge pipe of an unknown material through the levee, 20.5 feet below the crown. Gate valve on the waterside (WS) end. Pump on a pile structure in the stream. Wooden walkway to the pump. Concrete distribution box on the landside (LS). (Plans to demolish and remove the existing Meridian Diversion Pumping Facility and the existing Drexler Diversion Pumping Facility and to construct a new Meridian Diversion Pumping Facility with two retractable fish screens and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013						

LM Start	9.01	Rating **	M	Issue No.	106 (cont)
LM End	9.01	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24107_42457.jpg



View of waterward side--pump station and walkway.

Photo 2 of 3 : UCIP_SP_2018_24107_42458.jpg



View of 16-inch pipe and 24-inch pipe through levee on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	9.01	Rating **	M	Issue No.	106 (cont)	
LM End	9.01	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.110869 °	39.110869 °	
				-121.902771 °	-121.902771 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24107 DS_ID:21394 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: This pump station is to be demolished. This crossing will need to be updated once the work has been completed. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0433. FIELD_STRUCT_DESC: [Meridian Farms Water Company Pumping Plant No. 3] 3 of 3: 24-inch irrigation discharge pipe of an unknown material through the levee, 20.5 feet below the crown. Gate valve on the waterside (WS) end. Pump on a pile structure in the stream. Wooden walkway to the pump. Concrete distribution box on the landside (LS). (Plans to demolish and remove the existing Meridian Diversion Pumping Facility and the existing Drexler Diversion Pumping Facility and to construct a new Meridian Diversion Pumping Facility with two retractable fish screens and a 72-inch gravity feed intake pipe under the levee authorized under Permit No. 18762, 2013 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24107_42461.jpg



View of pipes located on waterward side.

LM Start	9.28	Rating **	M	Issue No.	61
LM End	9.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.107285 °	39.107285 °
				-121.900753 °	-121.900753 °
DWR ID	DWR_RD0070_02_f_2016_61				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_61_20180305_00010.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	9.57	Rating **	U	Issue No.	62
LM End	9.70	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.103192 °	39.101213 °
				-121.899606 °	-121.899380 °
DWR ID	DWR_RD0070_02_f_2016_62				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_62_20180305_00011.jpg



View of a ditch along the landside toe.

LM Start	9.69	Rating **	N	Issue No.	63	
LM End	9.69	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			39.101343 °		39.101343 °
				-121.899381 °		-121.899381 °
DWR ID	DWR_RD0070_02_f_2016_63					
Comment Code						
T5 : Tree stumps.						
Inspector Comment						

No Photos

LM Start	10.00	Rating **	M	Issue No.	4
LM End	10.00	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.097713 °	39.097713 °
				-121.896492 °	-121.896492 °
DWR ID	DWR_RD0070_02_s_2016_4				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.01	Rating **	M	Issue No.	5
LM End	10.40	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.097662 °	39.093662 °
				-121.896349 °	-121.892535 °
DWR ID	DWR_RD0070_02_s_2012_5				
Comment Code					
DT : Ditch					
Inspector Comment					

No Photos

LM Start	10.15	Rating **	M	Issue No.	107
LM End	10.15	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.096935 °	39.096935 °
				-121.893870 °	-121.893870 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23967 DS_ID:21396 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No evidence of pipe is visible on waterward side. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0477. FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe of an unknown material or purpose through the levee, 3.1 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Concrete plug on the LS end. Wooden distribution box on the LS at the discharge end. (Cat. IV-A). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 813+00)]. FS Date: 10/23/2013					

Photo 1 of 3 : UCIP_SP_2018_23967_42129.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.15	Rating **	M	Issue No.	107 (cont)
LM End	10.15	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.096935 °	39.096935 °
				-121.893870 °	-121.893870 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:23967 DS_ID:21396 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: No evidence of pipe is visible on waterward side. Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0477. FIELD_STRUCT_DESC: *ABANDONED* 12-inch pipe of an unknown material or purpose through the levee, 3.1 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Concrete plug on the LS end. Wooden distribution box on the LS at the discharge end. (Cat. IV-A). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 813+00)]. FS Date: 10/23/2013					

LM Start	10.15	Rating **	M	Issue No.	107 (cont)
LM End	10.15	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_23967_42132.jpg



No pipe exists levee on waterward side only CMP riser present on landward side.

Photo 3 of 3 : UCIP_SP_2018_23967_42131.jpg



CMP riser located on landward shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.40	Rating **	M	Issue No.	108
LM End	10.40	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.093712 °	39.093712 °
				-121.892553 °	-121.892553 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24195
DS_ID:21398
EP_NO: 1162
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to verify status of crossing--variation in pipe size. 18 inch pipe listed in desk study and 20 inch pipe found in field. Damage to siphon breaker housing unit. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0482.
FIELD_STRUCT_DESC: 1 of 2: 20-inch steel irrigation discharge pipe (not 18-inch, as referenced in the permit) through the levee, 3.7 feet below the crown. Concrete cutoff wall around the pipe at each shoulder. Siphon breaker in a steel pipe riser on the landside (LS) shoulder. Slant pump on a wooden pump structure on the waterside (WS). Corrugated metal pipe (CMP) riser under the pump structure at the WS toe. Distribution box at the LS toe. (Plans for the installation of two 18-inch steel discharge pipes through the levee and a pumping plant in the river authorized under Permit No. 1162, 1946 - Homer and Arthur Andreotti). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 824+00)].
FS Date: 10/23/2013

LM Start	10.40	Rating **	M	Issue No.	108 (cont)
LM End	10.40	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24195_42686.jpg



View of waterward side pathway behind power pole leads to pump station.

Photo 2 of 3 : UCIP_SP_2018_24195_42685.jpg



Pump station located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.40	Rating **	M	Issue No.	108 (cont)	
LM End	10.40	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.093712 °	39.093712 °	
				-121.892553 °	-121.892553 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24195 DS_ID:21398 EP_NO: 1162 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to verify status of crossing--variation in pipe size. 18 inch pipe listed in desk study and 20 inch pipe found in field. Damage to siphon breaker housing unit. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0482. FIELD_STRUCT_DESC: 1 of 2: 20-inch steel irrigation discharge pipe (not 18-inch, as referenced in the permit) through the levee, 3.7 feet below the crown. Concrete cutoff wall around the pipe at each shoulder. Siphon breaker in a steel pipe riser on the landside (LS) shoulder. Slant pump on a wooden pump structure on the waterside (WS). Corrugated metal pipe (CMP) riser under the pump structure at the WS toe. Distribution box at the LS toe. (Plans for the installation of two 18-inch steel discharge pipes through the levee and a pumping plant in the river authorized under Permit No. 1162, 1946 - Homer and Arthur Andreotti). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 824+00)]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24195_42688.jpg



View of landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.40	Rating **	M	Issue No.	109	
LM End	10.40	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.093699 °	39.093699 °	
				-121.892553 °	-121.892553 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24196 DS_ID:21430 EP_NO: 1162 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to verify status of crossing--variation in pipe size. 18 inch pipe listed in desk study and 20 inch pipe found in field. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0482. FIELD_STRUCT_DESC: 2 of 2: 20-inch steel irrigation discharge pipe (not 18-inch, as referenced in the permit) through the levee, 3.7 feet below the crown. Concrete cutoff wall around the pipe at each shoulder. Siphon breaker in a steel pipe riser on the landside (LS) shoulder. Slant pump on a wooden pump structure on the waterside (WS). Corrugated metal pipe (CMP) riser under the pump structure at the WS toe. Distribution box at the LS toe. (Plans for the installation of two 18-inch steel discharge pipes through the levee and a pumping plant in the river authorized under Permit No. 1162, 1946 - Homer and Arthur Andreotti). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 824+00)]. FS Date: 10/23/2013						

LM Start	10.40	Rating **	M	Issue No.	109 (cont)
LM End	10.40	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24196_42693.jpg



View of waterward side path to pump station is behind the power pole.

Photo 2 of 3 : UCIP_SP_2018_24196_42692.jpg



Pump station on waterward side dense vegetation on slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	10.40	Rating **	M	Issue No.	109 (cont)	
LM End	10.40	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.093699 °	39.093699 °	
				-121.892553 °	-121.892553 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24196 DS_ID:21430 EP_NO: 1162 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to verify status of crossing--variation in pipe size. 18 inch pipe listed in desk study and 20 inch pipe found in field. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0482. FIELD_STRUCT_DESC: 2 of 2: 20-inch steel irrigation discharge pipe (not 18-inch, as referenced in the permit) through the levee, 3.7 feet below the crown. Concrete cutoff wall around the pipe at each shoulder. Siphon breaker in a steel pipe riser on the landside (LS) shoulder. Slant pump on a wooden pump structure on the waterside (WS). Corrugated metal pipe (CMP) riser under the pump structure at the WS toe. Distribution box at the LS toe. (Plans for the installation of two 18-inch steel discharge pipes through the levee and a pumping plant in the river authorized under Permit No. 1162, 1946 - Homer and Arthur Andreotti). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 824+00)]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24196_42695.jpg



View of landward side--metal risers and concrete distribution box.

LM Start	11.07	Rating **	M	Issue No.	48
LM End	11.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.086098 °	39.086098 °
				-121.889988 °	-121.889988 °
DWR ID	DWR_RD0070_02_s_2018_48				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree from the waterside slope and toe.					

Photo 1 of 1 : SP_2018_RD0070_30_48_20180402_00128.jpg



View of the tree along the waterside slope and oe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	11.61	Rating **	M	Issue No.	110
LM End	11.61	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.080517 °	39.080517 °
				-121.890574 °	-121.890574 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:24197 DS_ID:21400 EP_NO: 9986 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0527. FIELD_STRUCT_DESC: *ABANDONED* 30-inch steel irrigation discharge pipe through the levee, 27.5 feet below the crown. Two electric gate valves in a concrete pit on the waterside (WS) end, at the end of the discharge pipe. Two slant pumps on the WS slope. Control switches in a corrugated metal shed at the WS shoulder. (Plans for the installation of two inclined turbine pumps, a gate valve, a 50-horsepower pump, and an electrical conduit authorized under Permit No. 5193, 1965 - Meridian Farms Water Company. Retention of a 30-inch steel pipe through the levee, 27.5 feet below the crown, two gate valves, two slant pumps, and a metal building with switch panels authorized under Automatic Board Order (ABO) issued as Permit No. 9986, 1974 - Meridian Farms Water Company. Plans to abolish existing pumping plant and to abandon existing pipeline at RM 125.8 and to construct a new pumping plant at RM 127.0 consisting of two 30-inch intake pipes supported by seven 10-inch by 10-inch H beams, a fish screen, and a 36-inch pipe trenched through the levee, and to place riprap on the slope authorized under Permit No. 18323, 2009 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 889+72)]. FS Date: 10/23/2013					

Photo 1 of 3 : UCIP_SP_2018_24197_42699.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	11.61	Rating **	M	Issue No.	110 (cont)
LM End	11.61	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.080517 °	39.080517 °
				-121.890574 °	-121.890574 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24197
 DS_ID:21400
 EP_NO: 9986
 Repair Type: Non-Urgent
 Crossing Status: Indicator Found
 UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0527.
 FIELD_STRUCT_DESC: *ABANDONED* 30-inch steel irrigation discharge pipe through the levee, 27.5 feet below the crown. Two electric gate valves in a concrete pit on the waterside (WS) end, at the end of the discharge pipe. Two slant pumps on the WS slope. Control switches in a corrugated metal shed at the WS shoulder. (Plans for the installation of two inclined turbine pumps, a gate valve, a 50-horsepower pump, and an electrical conduit authorized under Permit No. 5193, 1965 - Meridian Farms Water Company. Retention of a 30-inch steel pipe through the levee, 27.5 feet below the crown, two gate valves, two slant pumps, and a metal building with switch panels authorized under Automatic Board Order (ABO) issued as Permit No. 9986, 1974 - Meridian Farms Water Company. Plans to abolish existing pumping plant and to abandon existing pipeline at RM 125.8 and to construct a new pumping plant at RM 127.0 consisting of two 30-inch intake pipes supported by seven 10-inch by 10-inch H beams, a fish screen, and a 36-inch pipe trenched through the levee, and to place riprap on the slope authorized under Permit No. 18323, 2009 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 889+72)].
 FS Date: 10/23/2013

Photo 2 of 3 : UCIP_SP_2018_24197_42698.jpg



View of landward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	11.61	Rating **	M	Issue No.	110 (cont)
LM End	11.61	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.080517 °	39.080517 °
				-121.890574 °	-121.890574 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24197
DS_ID:21400
EP_NO: 9986
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Need to coordinate with owner to determine status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0527.
FIELD_STRUCT_DESC: *ABANDONED* 30-inch steel irrigation discharge pipe through the levee, 27.5 feet below the crown. Two electric gate valves in a concrete pit on the waterside (WS) end, at the end of the discharge pipe. Two slant pumps on the WS slope. Control switches in a corrugated metal shed at the WS shoulder. (Plans for the installation of two inclined turbine pumps, a gate valve, a 50-horsepower pump, and an electrical conduit authorized under Permit No. 5193, 1965 - Meridian Farms Water Company. Retention of a 30-inch steel pipe through the levee, 27.5 feet below the crown, two gate valves, two slant pumps, and a metal building with switch panels authorized under Automatic Board Order (ABO) issued as Permit No. 9986, 1974 - Meridian Farms Water Company. Plans to abolish existing pumping plant and to abandon existing pipeline at RM 125.8 and to construct a new pumping plant at RM 127.0 consisting of two 30-inch intake pipes supported by seven 10-inch by 10-inch H beams, a fish screen, and a 36-inch pipe trenched through the levee, and to place riprap on the slope authorized under Permit No. 18323, 2009 - Meridian Farms Water Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 889+72)].
FS Date: 10/23/2013

Photo 3 of 3 : UCIP_SP_2018_24197_42697.jpg



View of concrete slab with pump located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	---	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	11.61	Rating **	M	Issue No.	64
LM End	11.77	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		39.080505 °	39.079599 °	
			-121.890594 °	-121.893251 °	
DWR ID	DWR_RD0070_02_f_2016_64				
Comment Code					
DT : Ditch					
Inspector Comment					

No Photos

LM Start	12.26	Rating **	M	Issue No.	65
LM End	12.26	Issue Type +	En	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		39.073416 °	39.073416 °	
			-121.889254 °	-121.889254 °	
DWR ID	DWR_RD0070_02_f_2016_65				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_65_20180305_00012.jpg



View of a ditch along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.37	Rating **	M	Issue No.	111	
LM End	12.37	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.072540 °	39.072540 °	
				-121.887807 °	-121.887807 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:47033 DS_ID:21402 EP_NO: 9997 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris found on waterward side along berm running parallel to levee. Two crossing found--Need to coordinate with owner to determine permit for second crossing and status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0559. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 3.5 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Pump and control valve on the waterside (WS). Power pole on the WS shoulder. Discharge box at the LS toe. (Retention of a 12-inch steel pipe through the levee, 3.5 feet below the crown, a pump, a control valve, a siphon breaker, and a discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9997, 1974 - H. and Anne M. Rohleder). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 930+22)]. FS Date: 10/23/2013						

LM Start	12.37	Rating **	M	Issue No.	111 (cont)
LM End	12.37	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_47033_42141.jpg



Crossing appurtenances located near brush and power pole on waterward side.

Photo 2 of 3 : UCIP_SP_2018_47033_42139.jpg



Pipe crossing on waterward side. Second pipe comes out approximately 3 feet downstream from this crossing.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.37	Rating **	M	Issue No.	111 (cont)	
LM End	12.37	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.072540 °		39.072540 °
				-121.887807 °		-121.887807 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:47033 DS_ID:21402 EP_NO: 9997 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris found on waterward side along berm running parallel to levee. Two crossing found--Need to coordinate with owner to determine permit for second crossing and status of crossing. If crossing is no longer in use owner will need to contact the CVFPB to comply with Title 23. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0559. FIELD_STRUCT_DESC: 12-inch steel irrigation discharge pipe through the levee, 3.5 feet below the crown. Siphon breaker in a corrugated metal pipe (CMP) riser on the landside (LS) shoulder. Pump and control valve on the waterside (WS). Power pole on the WS shoulder. Discharge box at the LS toe. (Retention of a 12-inch steel pipe through the levee, 3.5 feet below the crown, a pump, a control valve, a siphon breaker, and a discharge box authorized under Automatic Board Order (ABO) issued as Permit No. 9997, 1974 - H. and Anne M. Rohleder). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 930+22)]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_47033_42143.jpg



Pipe section exposed unable to determine if it is still in use.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.43	Rating **	M	Issue No.	112
LM End	12.43	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.072480 °	39.072480 °
				-121.886540 °	-121.886540 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50086
DS_ID:24744
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 07/07/2016 Dense vegetation on both slopes. No damage was observed on levee slopes or crown, crossing was downgraded from Urgent to Non-Urgent. No permit found for crossing. Need to recheck during winter. According to Andy Duffey, District Representative, CVFPB has issued a enforcement letter to owner dated 6/23/2016. (DWR UCIP - omagana)10/23/2013 No records were found during initial desk study--need to contact owner to obtain permit number authorizing work. Owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 6-inch aluminum irrigation pipe sleeved through a 10-inch corrugated metal pipe through the levee, 1.5 feet below the crown. Annular space not grouted. Pipe extends down both slopes about 2 feet below the crown.
FS Date: 7/7/2016 10:39:00 AM

LM Start	12.43	Rating **	M	Issue No.	112 (cont)
LM End	12.43	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_50086_42883.jpg



View of pipe through levee--photo is from USACE PI Draft Report dated 6-2012.

Photo 2 of 3 : UCIP_SP_2018_50086_42882.jpg



View of pipe through levee--photo is from USACE PI Draft Report dated 6-2012.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.43	Rating **	M	Issue No.	112 (cont)	
LM End	12.43	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.072480 °	39.072480 °	
				-121.886540 °	-121.886540 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50086 DS_ID:24744 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 07/07/2016 Dense vegetation on both slopes. No damage was observed on levee slopes or crown, crossing was downgraded from Urgent to Non-Urgent. No permit found for crossing. Need to recheck during winter. According to Andy Duffey, District Representative, CVFPB has issued a enforcement letter to owner dated 6/23/2016. (DWR UCIP - omagana)10/23/2013 No records were found during initial desk study--need to contact owner to obtain permit number authorizing work. Owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 6-inch aluminum irrigation pipe sleeved through a 10-inch corrugated metal pipe through the levee, 1.5 feet below the crown. Annular space not grouted. Pipe extends down both slopes about 2 feet below the crown. FS Date: 7/7/2016 10:39:00 AM						

Photo 3 of 3 : UCIP_SP_2018_50086_42881.jpg



View of pipe through levee--photo is from USACE PI Draft Report dated 6-2012.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.46	Rating **	M	Issue No.	113
LM End	12.46	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.072512 °	39.072512 °	
			-121.886000 °	-121.886000 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:23984
DS_ID:21403
EP_NO: 3800
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Need to contact owner to determine if crossing is still active and to determine last inspection date. Will need copy of letter showing crossings passed inspection. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0568.
FIELD_STRUCT_DESC: 20-inch coated steel natural gas pipeline through the levee, 3 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Marker sign on the waterside (WS) shoulder. Natural gas equipment pad at the landside (LS) toe. (Plans to construct and maintain a 20-inch gas line across the Sacramento River authorized under Permit No. 3800, 1961 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007].
FS Date: 10/23/2013

LM Start	12.46	Rating **	M	Issue No.	113 (cont)
LM End	12.46	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_23984_42172.jpg



Marker located on waterward side.

Photo 2 of 3 : UCIP_SP_2018_23984_42171.jpg



Marker on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	12.46	Rating **	M	Issue No.	113 (cont)	
LM End	12.46	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.072512 °		39.072512 °
				-121.886000 °		-121.886000 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:23984 DS_ID:21403 EP_NO: 3800 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to contact owner to determine if crossing is still active and to determine last inspection date. Will need copy of letter showing crossings passed inspection. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0568. FIELD_STRUCT_DESC: 20-inch coated steel natural gas pipeline through the levee, 3 feet below the crown. Concrete cutoff wall around the pipe at the center of the levee. Marker sign on the waterside (WS) shoulder. Natural gas equipment pad at the landside (LS) toe. (Plans to construct and maintain a 20-inch gas line across the Sacramento River authorized under Permit No. 3800, 1961 - Pacific Gas and Electric Company [PG&E]). [Additional Reference(s): DWR Levee Log, 2007]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_23984_42170.jpg



Additional appurtenances located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	13.82	Rating **	M	Issue No.	114
LM End	13.82	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.068270 °	39.068270 °
				-121.862909 °	-121.862909 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:47039
DS_ID:21407
EP_NO: 9995
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Records show a 24-inch iron pipe through the waterward side along the old gaging station with the concrete struture located on the waterward slope.
FIELD_STRUCT_DESC: [Reclamation District No. 70 (RD0070) Drainage Plant] 1 of 5: 30-inch steel drainage discharge pipe through the levee at low elevation. Pipe is concrete encased under the crown, between the shoulders. Slide gate on the landside (LS). Flap gate in a secured structure on the waterside (WS) end. (Retention of a 30-inch steel drainage pipe through the levee, at low elevation, a slide gate, and a flap gate authorized under Automatic Board Order (ABO) issued as Permit No. 9995, 1974 - RD0070. Plans to construct a 10-foot by 12-foot by 19-foot concrete outlet structure on existing outlet pipes, to repair leaking pipes, to repair existing pumping plant, and to install sheet piling at the inlet ditch to allow continued operation of the pumping plant by the district authorized under Permit No. 13420, 1982 - RD0070). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 1007+10), referenced pipes at this location are 48 inches, 40 inches, and 50 inches].
FS Date: 10/23/2013

Photo 1 of 1 : UCIP_SP_2018_47039_42800.jpg



Remains of old gaging station associated with 24-inch iron pipe that extends into the river.

LM Start	13.82	Rating **	A/W	Issue No.	72
LM End	13.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.068370 °	39.068370 °
				-121.862763 °	-121.862763 °
DWR ID	DWR RD0070 02 s 2017 72				

Comment Code

E2 : Schedule repair of erosion site prior to the next inspection.

Inspector Comment

Repair the erosion along the waterside slope.

Photo 1 of 1 : SP_2018_RD0070_30_72_20180305_00015.jpg



View of the erosion along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75
LM End	13.83	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.068190 °	39.068190 °
				-121.862700 °	-121.862700 °
DWR ID	DWR_RD0070_02_f_2017_75				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:152					
Site Designation:RD 70-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/17/2017					
Notes: bank slope erosion around a drainage pipe/box					

LM Start	13.83	Rating **	A/W	Issue No.	75 (cont)
LM End	13.83	Issue Type +	Ma	Location *	

Photo 1 of 3 : LEVAL_SP_2018_152_1717.jpg



Photo 2 of 3 : LEVAL_SP_2018_152_1728.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75 (cont)	
LM End	13.83	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.068190°	39.068190°	
				-121.862700°	-121.862700°	
DWR ID	DWR_RD0070_02_f_2017_75					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:152						
Site Designation:RD 70-01						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes: bank slope erosion around a drainage pipe/box						

Photo 3 of 3 : LEVAL_SP_2018_152_1730.jpg



LM Start	14.14	Rating **	M	Issue No.	66
LM End	14.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.069849 °	39.069849 °
				-121.857267 °	-121.857267 °
DWR ID	DWR_RD0070_02_f_2016_66				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : SP_2018_RD0070_30_66_20180305_00013.jpg



View of slope instability along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

Reclamation District No. 0070 Meridian

Pump house located on waterward side.

Page 81 of 86

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	15.33	Rating **	M	Issue No.	115 (cont)	
LM End	15.33	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.065303 °	39.065303 °	
				-121.839230 °	-121.839230 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24229						
DS_ID:21421						
EP_NO: 9990						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Need to determine if crossings are still being used.						
This crossing is referenced in the USACE Periodic Inspection as item						
USACE_CESPK_MRD2_2012_p_0685.						
FIELD_STRUCT_DESC: 1 of 2: 24-inch steel irrigation discharge pipe						
sleeved through a 30-inch coated steel pipe through the levee, 24 feet						
below the crown. Gate valve on the waterside (WS) end. Concrete						
headwall with a flap gate on the landside (LS). Pump on a pile structure						
in the stream. Wooden walkway to the pump. (Retention of two 24-inch						
steel pipes through the levee, 24 feet below the crown, two pumps, and						
two gate valves authorized under Automatic Board Order (ABO) issued						
as Permit No. 9990, 1974 - Newhall Land and Farming Company).						
[Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento						
O&M Manual 134, June 1953, (Station 1086+55)].						
FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24229_42853.jpg



Overview of landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	15.34	Rating **	M	Issue No.	116
LM End	15.34	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.065294 °	39.065294 °
				-121.839215 °	-121.839215 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:24230
DS_ID:21409
EP_NO: 9990
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to determine if crossing is still being used. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0685.
FIELD_STRUCT_DESC: 2 of 2: 24-inch steel irrigation discharge pipe sleeved through a 30-inch coated steel pipe through the levee, 24 feet below the crown. Gate valve on the waterside (WS) end. Concrete headwall with a flap gate on the landside (LS). Pump on a pile structure in the stream. Wooden walkway to the pump. (Retention of two 24-inch steel pipes through the levee, 24 feet below the crown, two pumps, and two gate valves authorized under Automatic Board Order (ABO) issued as Permit No. 9990, 1974 - Newhall Land and Farming Company).
[Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 1086+55)].
FS Date: 10/23/2013

LM Start	15.34	Rating **	M	Issue No.	116 (cont)
LM End	15.34	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24230_42854.jpg



Walkway and Pump house located on waterward side.

Photo 2 of 3 : UCIP_SP_2018_24230_42855.jpg



Pump located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	15.34	Rating **	M	Issue No.	116 (cont)	
LM End	15.34	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.065294 °	39.065294 °	
				-121.839215 °	-121.839215 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24230 DS_ID:21409 EP_NO: 9990 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to determine if crossing is still being used. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0685. FIELD_STRUCT_DESC: 2 of 2: 24-inch steel irrigation discharge pipe sleeved through a 30-inch coated steel pipe through the levee, 24 feet below the crown. Gate valve on the waterside (WS) end. Concrete headwall with a flap gate on the landside (LS). Pump on a pile structure in the stream. Wooden walkway to the pump. (Retention of two 24-inch steel pipes through the levee, 24 feet below the crown, two pumps, and two gate valves authorized under Automatic Board Order (ABO) issued as Permit No. 9990, 1974 - Newhall Land and Farming Company). [Additional Reference(s): DWR Levee Log, 2007. USACE Sacramento O&M Manual 134, June 1953, (Station 1086+55)]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24230_42858.jpg



Overview of landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	15.34	Rating **	M	Issue No.	117
LM End	15.34	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.065285 °	39.065285 °
				-121.839202 °	-121.839202 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:24231 DS_ID:21420 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No daylight visible on landward side. Pipe was visible on waterward side. Need to contact owner to determine status of crossing. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0685. FIELD_STRUCT_DESC: 16-inch steel irrigation discharge pipe through the levee, approximately 15 feet below the crown. Gate valves on the waterside (WS) end. Pumps on the WS. [Additional Reference(s): USACE Sacramento O&M Manual 134, June 1953, (Station 1086+55)]. FS Date: 10/23/2013					

LM Start	15.34	Rating **	M	Issue No.	117 (cont)
LM End	15.34	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_24231_42859.jpg



Walkway and structure located on waterward side.

Photo 2 of 3 : UCIP_SP_2018_24231_42863.jpg



View of landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	15.34	Rating **	M	Issue No.	117 (cont)	
LM End	15.34	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.065285 °	39.065285 °	
				-121.839202 °	-121.839202 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:24231 DS_ID:21420 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No daylight visible on landward side. Pipe was visible on waterward side. Need to contact owner to determine status of crossing. This crossing is referenced in the USACE Periodic Inspection as item USACE_CESPK_MRD2_2012_p_0685. FIELD_STRUCT_DESC: 16-inch steel irrigation discharge pipe through the levee, approximately 15 feet below the crown. Gate valves on the waterside (WS) end. Pumps on the WS. [Additional Reference(s): USACE Sacramento O&M Manual 134, June 1953, (Station 1086+55)]. FS Date: 10/23/2013						

Photo 3 of 3 : UCIP_SP_2018_24231_42860.jpg



View of landward side photo taken from concrete headwall.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---